

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator ID Number NJD086630705	2. Page 1 of 1	3. Emergency Response Phone (203)238-6745	4. Manifest Tracking Number 011519380 JJK		
5. Generator's Name and Mailing Address US EPA Region II 2690 Woodbridge Ave - Edison, NJ 08837 Generator's Phone: 732 321-4350			Generator's Site Address (if different than mailing address) US EPA Reg II /Superior B 798 Jacob Harris Lane Glassboro, NJ 08028				
6. Transporter 1 Company Name Tradebe Transportation, LLC			U.S. EPA ID Number CTD021816889				
7. Transporter 2 Company Name			U.S. EPA ID Number				
8. Designated Facility Name and Site Address Tradebe Treatment and Recycling Northsast, LLC 136 GRACEY AVENUE - MERIDEN, CT 06451 Facility's Phone: 203 2386745			U.S. EPA ID Number CTD021816889				
9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))		10. Containers		11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes
			No.	Type			
	1. UN1993, WASTE, FLAMMABLE LIQUIDS, N.O.S. (Methyl Ethyl Ketone, Toluene), 3, PGIII, RQ		001	TT	4,500	G	D001 D035 D040 D008
	2.						
	3.						
4.							
14. Special Handling Instructions and Add EMERGENCY PHI T&D Subcontract # 1							
15. GENERATOR'S/OFFEROR'S CERTIFICATE marked and labeled/placarded, and Exporter, I certify that the contents of this manifest are correct and that the waste minimization program is being followed. Generator's/Officer's Printed/Typed Name Kenneth Coleman I am classified, packaged, labeled, and I am the Primary							
16. International Shipments <input type="checkbox"/> Transporter signature (for exports only):							
17. Transporter Acknowledgment of Receipt Transporter 1 Printed/Typed Name Timothy Transporter 2 Printed/Typed Name							
18. Discrepancy 18a. Discrepancy Indication Space Trailer #3 Part of Line Item A of subcontract #1 50 containers 12 totes 38 drums							
18b. Alternate Facility (or Generator) Name and Address Facility's Phone:							
18c. Signature of Alternate Facility							
19. Hazardous Waste Report Manifest 1. 50 containers 2. 12 totes 3. 38 drums							
20. Designated Facility Owner or Operator Printed/Typed Name							
Manifest Reference Number: 310412 U.S. EPA ID Number Month Day Year 3 7 14 Month Day Year 3 7 14 Month Day Year 3 7 14							
Signature Month Day Year							

U.S. EPA Form 8700-22

Read all instructions before completing this form.

- This form has been designed for use on a 12-pitch (elite) typewriter which is also compatible with standard computer printers; a firm point pen may also be used—press down hard.
- Federal regulations require generators and transporters of hazardous waste and owners or operators of hazardous waste treatment, storage, and disposal facilities to complete this form (EPA Form 8700-22) and, if necessary, the continuation sheet (EPA Form 8700-22A) for both inter- and intrastate transportation of hazardous waste.

Public reporting burden for this collection of information is estimated to average: 30 minutes for generators; 10 minutes for transporters, and 25 minutes for owners or operators of treatment, storage, and disposal facilities. This includes time for reviewing instructions, gathering data, completing, reviewing and transmitting the form. Any correspondence regarding the PRA burden statement for the manifest must be sent to the Director of the Collection Strategies Division in EPA's Office of Information Collection at the following address: U.S. Environmental Protection Agency (2822T), 1200 Pennsylvania Ave., NW., Washington, DC 20460. Do not send the completed form to this address.

I. Instructions for Generators

Item 1. Generator's U.S. EPA Identification Number

Enter the generator's U.S. EPA twelve digit identification number, or the State generator identification number if the generator site does not have an EPA identification number.

Item 2. Page 1 of

Enter the total number of pages used to complete this Manifest (i.e., the first page (EPA Form 8700-22) plus the number of Continuation Sheets (EPA Form 8700-22A), if any).

Item 3. Emergency Response Phone Number

Enter a phone number for which emergency response information can be obtained in the event of an incident during transportation. The emergency response phone number must:

- Be the number of the generator or the number of an agency or organization who is capable of and accepts responsibility for providing detailed information about the shipment;
- Reach a phone that is monitored 24 hours a day at all times the waste is in transportation (including transportation related storage); and
- Reach someone who is either knowledgeable of the hazardous waste being shipped and has comprehensive emergency response and spill cleanup/incident mitigation information for the material being shipped or has immediate access to a person who has that knowledge and information about the shipment.

Note: Emergency Response phone number information should only be entered in Item 3 when there is one phone number that applies to all the waste materials described in Item 9b. If a situation (e.g., consolidated shipments) arises where more than one Emergency Response phone number applies to the various wastes listed on the manifest, the phone numbers associated with each specific material should be entered after its description in Item 9b.

Item 4. Manifest Tracking Number

This unique tracking number must be pre-printed on the manifest by the forms printer.

Item 5. Generator's Mailing Address, Phone Number and Site Address

Enter the name of the generator, the mailing address to which the completed manifest signed by the designated facility should be mailed, and the generator's telephone number. Note, the telephone number (including area code) should be the normal business number for the generator, or the number where the generator or his authorized agent may be reached to provide instructions in the event the designated and/or alternate (if any) facility rejects some or all of the shipment. Also enter the physical site address from which the shipment originates only if this address is different than the mailing address.

Item 6. Transporter 1 Company Name, and U.S. EPA ID Number

Enter the company name and U.S. EPA ID number of the first transporter who will transport the waste. Vehicle or driver information may not be entered here.

Item 7. Transporter 2 Company Name and U.S. EPA ID Number

If applicable, enter the company name and U.S. EPA ID number of the second transporter who will transport the waste. Vehicle or driver information may not be entered here.

If more than two transporters are needed, use a Continuation Sheet(s) (EPA Form 8700-22A).

Item 8. Designated Facility Name, Site Address, and U.S. EPA ID Number

Enter the company name and site address of the facility designated to receive the waste listed on this manifest. Also enter the facility's phone number and the U.S. EPA twelve digit identification number of the facility.

Item 9. U.S. DOT Description (Including Proper Shipping Name, Hazard Class or Division, Identification Number, and Packing Group)

Item 9a. If the wastes identified in Item 9b consist of both hazardous and nonhazardous materials, then identify the hazardous materials by entering an "X" in this Item next to the corresponding hazardous material identified in Item 9b.

Item 9b. Enter the U.S. DOT Proper Shipping Name, Hazard Class or Division, Identification Number (UN/NA) and Packing Group for each waste as identified in 49 CFR 172. Include technical name(s) and reportable quantity references, if applicable.

Note: If additional space is needed for waste descriptions, enter these additional descriptions in Item 27 on the Continuation Sheet (EPA Form 8700-22A). Also, if more than one Emergency Response phone number applies to the various wastes described in either Item 9b or Item 27, enter applicable Emergency Response phone numbers immediately following the shipping descriptions for those items.

Item 10. Containers (Number and Type)

Enter the number of containers for each waste and the appropriate abbreviation from Table I (below) for the type of container.

TABLE I.—TYPES OF CONTAINERS

BA = Burlap, cloth, paper, or plastic bags.	DT = Dump truck.
CF = Fiber or plastic boxes, cartons, cases.	DW = Wooden drums, barrels, kegs.
CM = Metal boxes, cartons, cases (including roll-offs).	HG = Hopper or gondola cars.
CW = Wooden boxes, cartons, cases.	TC = Tank cars.
CY = Cylinders.	TP = Portable tanks.
DF = Fiberboard or plastic drums, barrels, kegs.	TT = Cargo tanks (tank trucks).
DM = Metal drums, barrels, kegs.	

Item 11. Total Quantity

Enter, in designated boxes, the total quantity of waste. Round partial units to the nearest whole unit, and do not enter decimals or fractions. To the extent practical, report quantities using appropriate units of measure that will allow you to report quantities with precision. Waste quantities entered should be based on actual measurements or reasonably accurate estimates of actual quantities shipped. Container capacities are not acceptable as estimates.

Item 12. Units of Measure (Weight/Volume)

Enter, in designated boxes, the appropriate abbreviation from Table II (below) for the unit of measure.

TABLE II.—UNITS OF MEASURE

G = Gallons (liquids only).	N = Cubic Meters.
K = Kilograms.	P = Pounds.
L = Liters (liquids only).	T = Tons (2000 Pounds).
M = Metric Tons (1000 kilograms).	Y = Cubic Yards.

Note: Tons, Metric Tons, Cubic Meters, and Cubic Yards should only be reported in connection with very large bulk shipments, such as rail cars, tank trucks, or barges.

Item 13. Waste Codes

Enter up to six federal and state waste codes to describe each waste stream identified in Item 9b. State waste codes that are not redundant with federal codes must be entered here, in addition to the federal waste codes which are most representative of the properties of the waste.

Item 14. Special Handling Instructions and Additional Information

- Generators may enter any special handling or shipment-specific information necessary for the proper management or tracking of the materials under the generator's or other handler's business processes, such as waste profile numbers, container codes, bar codes, or response guide numbers. Generators also may use this space to enter additional descriptive information about their shipped materials, such as chemical names, constituent percentages, physical state, or specific gravity of wastes identified with volume units in Item 12.
- This space may be used to record limited types of federally required information for which there is no specific space provided on the manifest, including any alternate facility designations; the manifest tracking number of the original manifest for rejected wastes; and residues that are re-shipped under a second manifest; and the specification of PCB waste descriptions and PCB out-of-service dates required under 40 CFR 761.207. Generators, however, cannot be required to enter information in this space to meet state regulatory requirements.

Item 15. Generator's/Officer's Certifications

- The generator must read, sign, and date the waste minimization certification statement. In signing the waste minimization certification statement, those generators who have not been exempted by statute or regulation from the duty to make a waste minimization certification under section 3002(b) of RCRA are also certifying that they have complied with the waste minimization requirements. The Generator's Certification also contains the required attestation that the shipment has been properly prepared and is in proper condition for transportation (the shipper's certification). The content of the shipper's certification statement is as follows: "I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent." When a party other than the generator prepares the shipment for transportation, this party may also sign the shipper's certification statement as the offeror of the shipment.
- Generator or Offeror personnel may preprint the words, "On behalf of" in the signature block or may hand write this statement in the signature block prior to signing the generator/offeror certification, to indicate that the individual signs as the employee or agent of the named principal.

Note: All of the above information except the handwritten signature required in Item 15 may be pre-printed.



1 of 2

Generator / Location: USPA US CPA Reg 11 / Superior B

EPA ID: NJD986630705

Manifest: 011519880 JJK

☐ YES ☐ NO ☐ On File at Facility

I CERTIFY UNDER PENALTY OF LAW THAT THE ABOVE INFORMATION IS ACCURATE AND TRUE

Print: Keith Glenn

Date: 3/7/2014

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator ID Number NJD986630705	2. Page 1 of 1	3. Emergency Response Phone (203)238-6745	4. Manifest Tracking Number 011519349 JJK				
5. Generator's Name and Mailing Address US EPA Region II 2890 Woodbridge Ave - Edison, NJ 08837			Generator's Site Address (if different than mailing address) US EPA Reg II / Superior B 798 Jacob Harris Lane Glassboro, NJ 08028						
Generator's Phone: 732 321-4350-4454									
6. Transporter 1 Company Name Tradebe Transportation, LLC				U.S. EPA ID Number CTD021816889					
7. Transporter 2 Company Name				U.S. EPA ID Number					
8. Designated Facility Name and Site Address Tradebe Treatment and Recycling Northeast, LLC 138 GRACEY AVENUE - MERIDEN, CT 06451				U.S. EPA ID Number CTD021816889					
Facility's Phone: 203 2386745									
GENERATOR	9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	10. Containers		11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes		
			No.	Type					
	1.	UN1983, WASTE, FLAMMABLE LIQUIDS, N.O.S. (Methyl Ethyl Ketone, Toluene), 3, PGIII, RQ	001	TT	5000	G	D001 D035 D040 D008		
	2.								
	3.								
14. Special Handling Instructions and Additional Information EMERGENCY PH# (203)238-6745 101D# 4937C 1) ERG # 128 - P022114016FL									
15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.									
Generator's/Offor's Printed/Typed Name Keith Green (Agent for US EPA)			Signature <i>[Signature]</i>			Month 03	Day 05	Year 11	
TRANSPORTER	16. International Shipments <input type="checkbox"/> Import to U.S. <input type="checkbox"/> Export from U.S.		Port of entry/exit: Date leaving U.S.:						
	Transporter signature (for exports only):								
DESIGNATED FACILITY	17. Transporter Acknowledgment of Receipt of Materials								
	Transporter 1 Printed/Typed Name Douglas Andrews			Signature <i>[Signature]</i>			Month 09	Day 05	Year 11
	Transporter 2 Printed/Typed Name			Signature			Month	Day	Year
	18. Discrepancy								
	18a. Discrepancy Indication Space <input type="checkbox"/> Quantity <input type="checkbox"/> Type <input type="checkbox"/> Residue <input type="checkbox"/> Partial Rejection <input type="checkbox"/> Full Rejection								
	Manifest Reference Number:								
	18b. Alternate Facility (or Generator) U.S. EPA ID Number								
	Facility's Phone:								
	18c. Signature of Alternate Facility (or Generator) Month Day Year								
	19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)								
	1.	2.	3.	4.					
	20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a								
	Printed/Typed Name			Signature			Month	Day	Year

U.S. EPA Form 8700-22

Read all instructions before completing this form.

1. This form has been designed for use on a 12-pitch (elite) typewriter which is also compatible with standard computer printers; a firm point pen may also be used—press down hard.
2. Federal regulations require generators and transporters of hazardous waste and owners or operators of hazardous waste treatment, storage, and disposal facilities to complete this form (EPA Form 8700-22) and, if necessary, the continuation sheet (EPA Form 8700-22A) for both inter- and intrastate transportation of hazardous waste.

Public reporting burden for this collection of information is estimated to average: 30 minutes for generators, 10 minutes for transporters, and 25 minutes for owners or operators of treatment, storage, and disposal facilities. This includes time for reviewing instructions, gathering data, completing, reviewing and transmitting the form. Any correspondence regarding the PRA burden statement for the manifest must be sent to the Director of the Collection Strategies Division in EPA's Office of Information Collection at the following address: U.S. Environmental Protection Agency (2822T), 1200 Pennsylvania Ave., NW., Washington, DC 20460. Do not send the completed form to this address.

I. Instructions for Generators

Item 1. Generator's U.S. EPA Identification Number

Enter the generator's U.S. EPA twelve digit identification number, or the State generator identification number if the generator site does not have an EPA identification number.

Item 2. Page 1 of ____

Enter the total number of pages used to complete this Manifest (i.e., the first page (EPA Form 8700-22) plus the number of Continuation Sheets (EPA Form 8700-22A), if any).

Item 3. Emergency Response Phone Number

Enter a phone number for which emergency response information can be obtained in the event of an incident during transportation. The emergency response phone number must:

1. Be the number of the generator or the number of an agency or organization who is capable of and accepts responsibility for providing detailed information about the shipment;
2. Reach a phone that is monitored 24 hours a day at all times the waste is in transportation (including transportation related storage); and
3. Reach someone who is either knowledgeable of the hazardous waste being shipped and has comprehensive emergency response and spill cleanup/incident mitigation information for the material being shipped or has immediate access to a person who has that knowledge and information about the shipment.

Note: Emergency Response phone number information should only be entered in Item 3 when there is one phone number that applies to all the waste materials described in Item 9b. If a situation (e.g., consolidated shipments) arises where more than one Emergency Response phone number applies to the various wastes listed on the manifest, the phone numbers associated with each specific material should be entered after its description in Item 9b.

Item 4. Manifest Tracking Number

This unique tracking number must be pre-printed on the manifest by the forms printer.

Item 5. Generator's Mailing Address, Phone Number and Site Address

Enter the name of the generator, the mailing address to which the completed manifest signed by the designated facility should be mailed, and the generator's telephone number. Note, the telephone number (including area code) should be the normal business number for the generator, or the number where the generator or his authorized agent may be reached to provide instructions in the event the designated and/or alternate (if any) facility rejects some or all of the shipment. Also enter the physical site address from which the shipment originates only if this address is different than the mailing address.

Item 6. Transporter 1 Company Name, and U.S. EPA ID Number

Enter the company name and U.S. EPA ID number of the first transporter who will transport the waste. Vehicle or driver information may not be entered here.

Item 7. Transporter 2 Company Name and U.S. EPA ID Number

If applicable, enter the company name and U.S. EPA ID number of the second transporter who will transport the waste. Vehicle or driver information may not be entered here.

If more than two transporters are needed, use a Continuation Sheet(s) (EPA Form 8700-22A).

Item 8. Designated Facility Name, Site Address, and U.S. EPA ID Number

Enter the company name and site address of the facility designated to receive the waste listed on this manifest. Also enter the facility's phone number and the U.S. EPA twelve digit identification number of the facility.

Item 9. U.S. DOT Description (Including Proper Shipping Name, Hazard Class or Division, Identification Number, and Packing Group)

Item 9a. If the wastes identified in Item 9b consist of both hazardous and nonhazardous materials, then identify the hazardous materials by entering an "X" in this Item next to the corresponding hazardous material identified in Item 9b.

Item 9b. Enter the U.S. DOT Proper Shipping Name, Hazard Class or Division, Identification Number (UN/NA) and Packing Group for each waste as identified in 49 CFR 172. Include technical name(s) and reportable quantity references, if applicable.

Note: If additional space is needed for waste descriptions, enter these additional descriptions in Item 27 on the Continuation Sheet (EPA Form 8700-22A). Also, if more than one Emergency Response phone number applies to the various wastes described in either Item 9b or Item 27, enter applicable Emergency Response phone numbers immediately following the shipping descriptions for those Items.

Item 10. Containers (Number and Type)

Enter the number of containers for each waste and the appropriate abbreviation from Table I (below) for the type of container.

TABLE I - TYPES OF CONTAINERS

BA = Burlap, cloth
CF = Fiber or cloth
CM = Metal box, roll-offs)
CW = Wooden
CY = Cylinders
DF = Fiberboard
DM = Metal drum

Tanker #2

*Part of Line Item A
on Subcontract #1*

Item 11. Total Quantity

Enter, in designated whole unit, and do not use appropriate units. Waste quantities enter estimates of actual quantity.

Item 12. Units of Measure

Enter, in designated box, measure.

G = Gallons (liquids only).
K = Kilograms.
L = Liters (liquids only).
M = Metric Tons (1000 kilograms).
Y = Cubic Yards.

*55 containers
- 13 totes
- 42 drums*

Note: Tons, Metric Tons, Cubic Meters, and Cubic Yards should only be reported in connection with very large bulk shipments, such as rail cars, tank trucks, or barges.

Item 13. Waste Codes

Enter up to six federal and state waste codes to describe each waste stream identified in Item 9b. State waste codes that are not redundant with federal codes must be entered here, in addition to the federal waste codes which are most representative of the properties of the waste.

Item 14. Special Handling Instructions and Additional Information

1. Generators may enter any special handling or shipment-specific information necessary for the proper management or tracking of the materials under the generator's or other handler's business processes, such as waste profile numbers, container codes, bar codes, or response guide numbers. Generators also may use this space to enter additional descriptive information about their shipped materials, such as chemical names, constituent percentages, physical state, or specific gravity of wastes identified with volume units in Item 12.
2. This space may be used to record limited types of federally required information for which there is no specific space provided on the manifest, including any alternate facility designations; the manifest tracking number of the original manifest for rejected wastes and residues that are re-shipped under a second manifest; and the specification of PCB waste descriptions and PCB out-of-service dates required under 40 CFR 761.207. Generators, however, cannot be required to enter information in this space to meet state regulatory requirements.

Item 15. Generator's/Officer's Certifications

1. The generator must read, sign, and date the waste minimization certification statement. In signing the waste minimization certification statement, those generators who have not been exempted by statute or regulation from the duty to make a waste minimization certification under section 3002(b) of RCRA are also certifying that they have complied with the waste minimization requirements. The Generator's Certification also contains the required attestation that the shipment has been properly prepared and is in proper condition for transportation (the shipper's certification). The content of the shipper's certification statement is as follows: "I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent." When a party other than the generator prepares the shipment for transportation, this party may also sign the shipper's certification statement as the offeror of the shipment.
2. Generator or Offeror personnel may preprint the words, "On behalf of" in the signature block or may hand write this statement in the signature block prior to signing the generator/officer certification, to indicate that the individual signs as the employee or agent of the named principal.

Note: All of the above information except the handwritten signature required in Item 15 may be pre-printed.



1 of 2

Manifest: 011519349JJK

Waste Analysis Available? ☐ YES ☐ NO ☐ On File at Facility

Title: EPA OSC Date: 3/5/2014



2 of 2

EPA ID: NJD986630705

Manifest: 011519349JJK

Waste Analysis Available? ☐ YES ☐ NO ☐ On File at Facility

[illegible]

Authorized signature: Keith Glenn Print: Keith Glenn

Title: EPA OSC Date: 3/5/2014

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator, ID Number NJD986630705	2. Page 1 of 1	3. Emergency Response Phone (203)238-6745	4. Manifest Tracking Number 011519302 JJK	
5. Generator's Name and Mailing Address US EPA Region II 2880 Woodbridge Ave - Edison, NJ 08837 Generator's Phone: 732 321-4360 321-4454			Generator's Site Address (if different than mailing address) US EPA Reg II / Superior B 798 Jacob Harris Lane Glassboro, NJ 08028			
6. Transporter 1 Company Name Tradebe Transportation, LLC			U.S. EPA ID Number CTD021816889			
7. Transporter 2 Company Name			U.S. EPA ID Number			
8. Designated Facility Name and Site Address Tradebe Treatment and Recycling Northeast, LLC 136 GRACEY AVENUE - MERIDEN, CT 06451 203 2386745 Facility's Phone:			U.S. EPA ID Number CTD021816889			
9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	10. Containers No.	Type	11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes
X	1. UN1993, WASTE, FLAMMABLE LIQUIDS, N.O.S. (Methyl Ethyl Ketone, Toluene), 3, PGIII, RQ	001	TT	4700	G	D001 D035 D040 D008
	2.					
	3.					
	4.					
14. Special Handling Instructions and Additional Information EMERGENCY PH# (203)238-6745 1) ERG # 128 - P022T14016FL ET 4700						
15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.						
Generator's/Offeror's Printed/Typed Name Keith Glavin (Agent for US EPA)		Signature <i>[Signature]</i>		Month Day Year 02 28 14		
16. International Shipments <input type="checkbox"/> Import to U.S. <input type="checkbox"/> Export from U.S.		Port of entry/exit: Date leaving U.S.:				
17. Transporter Acknowledgment of Receipt of Materials						
Transporter 1 Printed/Typed Name Chris Brown		Signature <i>[Signature]</i>		Month Day Year 02 28 14		
Transporter 2 Printed/Typed Name		Signature		Month Day Year		
18. Discrepancy						
18a. Discrepancy Indication Space <input type="checkbox"/> Quantity <input type="checkbox"/> Type <input type="checkbox"/> Residue <input type="checkbox"/> Partial Rejection <input type="checkbox"/> Full Rejection						
18b. Alternate Facility (or Generator) Manifest Reference Number: U.S. EPA ID Number						
18c. Signature of Alternate Facility (or Generator) Month Day Year						
19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems) 1. 2. 3.						
20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 19. Printed/Typed Name Signature 27 Cont						

U.S. EPA Form 8700-22

Read all instructions before completing this form.

1. This form has been designed for use on a 12-pitch (elite) typewriter which is also compatible with standard computer printers; a firm point pen may also be used—press down hard.
2. Federal regulations require generators and transporters of hazardous waste and owners or operators of hazardous waste treatment, storage, and disposal facilities to complete this form (EPA Form 8700-22) and, if necessary, the continuation sheet (EPA Form 8700-22A) for both inter- and intrastate transportation of hazardous waste.

Public reporting burden for this collection of information is estimated to average: 30 minutes for generators, 10 minutes for transporters, and 25 minutes for owners or operators of treatment, storage, and disposal facilities. This includes time for reviewing instructions, gathering data, completing, reviewing and transmitting the form. Any correspondence regarding the PRA burden statement for the manifest must be sent to the Director of the Collection Strategies Division in EPA's Office of Information Collection at the following address: U.S. Environmental Protection Agency (2822T), 1200 Pennsylvania Ave., NW., Washington, DC 20460. Do not send the completed form to this address.

I. Instructions for Generators

Item 1. Generator's U.S. EPA Identification Number

Enter the generator's U.S. EPA twelve digit identification number, or the State generator identification number if the generator site does not have an EPA identification number.

Item 2. Page 1 of ____

Enter the total number of pages used to complete this Manifest (i.e., the first page (EPA Form 8700-22) plus the number of Continuation Sheets (EPA Form 8700-22A); if any).

Item 3. Emergency Response Phone Number

Enter a phone number for which emergency response information can be obtained in the event of an incident during transportation. The emergency response phone number must:

1. Be the number of the generator or the number of an agency or organization who is capable of and accepts responsibility for providing detailed information about the shipment;
2. Reach a phone that is monitored 24 hours a day at all times the waste is in transportation (including transportation related storage); and
3. Reach someone who is either knowledgeable of the hazardous waste being shipped and has comprehensive emergency response and spill cleanup/incident mitigation information for the material being shipped or has immediate access to a person who has that knowledge and information about the shipment.

Note: Emergency Response phone number information should only be entered in Item 3 when there is one phone number that applies to all the waste materials described in Item 9b. If a situation (e.g., consolidated shipments) arises where more than one Emergency Response phone number applies to the various wastes listed on the manifest, the phone numbers associated with each specific material should be entered after its description in Item 9b.

Item 4. Manifest Tracking Number

This unique tracking number must be pre-printed on the manifest by the forms printer.

Item 5. Generator's Mailing Address, Phone Number and Site Address

Enter the name of the generator, the mailing address to which the completed manifest signed by the designated facility should be mailed, and the generator's telephone number. Note, the telephone number (including area code) should be the normal business number for the generator, or the number where the generator or his authorized agent may be reached to provide instructions in the event the designated and/or alternate (if any) facility rejects some or all of the shipment. Also enter the physical site address from which the shipment originates only if this address is different than the mailing address.

Item 6. Transporter 1 Company Name, and U.S. EPA ID Number

Enter the company name and U.S. EPA ID number of the first transporter who will transport the waste. Vehicle or driver information may not be entered here.

Item 7. Transporter 2 Company Name and U.S. EPA ID Number

If applicable, enter the company name and U.S. EPA ID number of the second transporter who will transport the waste. Vehicle or driver information may not be entered here.

If more than two transporters are needed, use a Continuation Sheet(s) (EPA Form 8700-22A).

Item 8. Designated Facility Name, Site Address, and U.S. EPA ID Number

Enter the company name and site address of the facility designated to receive the waste listed on this manifest. Also enter the facility's phone number and the U.S. EPA twelve digit identification number of the facility.

Item 9. U.S. DOT Description (Including Proper Shipping Name, Hazard Class or Division, Identification Number, and Packing Group)

If the wastes identified in Item 9b consist of both hazardous and nonhazardous materials, then identify the hazardous materials by entering an "X" in this Item next to the hazardous material identified in Item 9b.

For each waste as identified in 49 CFR 172. Include U.S. DOT Proper Shipping Name, Hazard Class or Division, Identification Number, and Packing Group for each waste as identified in 49 CFR 172. Include additional descriptions, if applicable. Also, if more than one waste is identified in either Item 9b or Item 9c, enter these additional descriptions following the same format as above.

Item 10. Containers (Number and Type)

Enter the number of containers for each waste and the appropriate abbreviation from Table I (below) for the type of container.

TABLE I.—TYPES OF CONTAINERS

BA = Burlap, cloth, paper, or plastic bags.	DT = Dump truck.
CF = Fiber or plastic boxes, cartons, cases.	DW = Wooden drums, barrels, kegs.
CM = Metal boxes, cartons, cases (including roll-offs).	HG = Hopper or gondola cars.
CW = Wooden boxes, cartons, cases.	TC = Tank cars.
CY = Cylinders.	TP = Portable tanks.
DF = Fiberboard or plastic drums, barrels, kegs.	TT = Cargo tanks (tank trucks).
DM = Metal drums, barrels, kegs.	

Item 11. Total Quantity

Enter, in designated boxes, the total quantity of waste. Round partial units to the nearest whole unit, and *do not* enter decimals or fractions. To the extent practical, report quantities using appropriate units of measure that will allow you to report quantities with precision. Waste quantities entered should be based on actual measurements or reasonably accurate estimates of actual quantities shipped. Container capacities are not acceptable as estimates.

Item 12. Units of Measure (Weight/Volume)

Enter, in designated boxes, the appropriate abbreviation from Table II (below) for the unit of measure.

TABLE II.—UNITS OF MEASURE

G = Gallons (liquids only).	N = Cubic Meters.
K = Kilograms.	P = Pounds.
L = Liters (liquids only).	T = Tons (2000 Pounds).
M = Metric Tons (1000 kilograms).	Y = Cubic Yards.

Note: Tons, Metric Tons, Cubic Meters, and Cubic Yards should only be reported in connection with very large bulk shipments, such as rail cars, tank trucks, or barges.

Item 13. Waste Codes

Enter up to six federal and state waste codes to describe each waste stream identified in Item 9b. State waste codes that are not redundant with federal codes must be entered here, in addition to the federal waste codes which are most representative of the properties of the waste.

Item 14. Special Handling Instructions and Additional Information

1. Generators may enter any special handling or shipment-specific information necessary for the proper management or tracking of the materials under the generator's or other handler's business processes, such as waste profile numbers, container codes, bar codes, or response guide numbers. Generators also may use this space to enter additional descriptive information about their shipped materials, such as chemical names, constituent percentages, physical state, or specific gravity of wastes identified with volume units in Item 12.
2. This space may be used to record limited types of federally required information for which there is no specific space provided on the manifest, including any alternate facility designations; the manifest tracking number of the original manifest for rejected wastes and residues that are re-shipped under a second manifest; and the specification of PCB waste descriptions and PCB out-of-service dates required under 40 CFR 761.207. Generators, however, cannot be required to enter information in this space to meet state regulatory requirements.

Item 15. Generator's/Officer's Certifications

1. The generator must read, sign, and date the waste minimization certification statement. In signing the waste minimization certification statement, those generators who have not been exempted by statute or regulation from the duty to make a waste minimization certification under section 3002(b) of RCRA are also certifying that they have complied with the waste minimization requirements. The Generator's Certification also contains the required attestation that the shipment has been properly prepared and is in proper condition for transportation (the shipper's certification). The content of the shipper's certification statement is as follows: "I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent." When a party other than the generator prepares the shipment for transportation, this party may also sign the shipper's certification statement as the offeror of the shipment.
2. Generator or Offeror personnel may preprint the words, "On behalf of" in the signature block or may hand write this statement in the signature block prior to signing the generator/offeror certification, to indicate that the individual signs as the employee or agent of the named principal.

Note: All of the above information except the handwritten signature required in Item 15 may be pre-printed.



TRADEBE
Environmental Services™

J0227140043-101

136 Gracey Avenue
MERIDEN, CT 06451
TELEPHONE: (203) 238-8745
www.tradebeusa.com

BILLING:

American Waste New Jersey LLC
One American Way
Warren, OH 44484

SITE:

US EPA Reg II /Superior Barrel & DM
798 Jacob Harris Lane
Glassboro, NJ 08028

Job ID: J0227140043-101 (1 of 1)
Scheduled For: 2/28/2014
Requested Time: 7:30:00 AM - 8:30:00 AM
Preferred Time
CS Rep: Massaro, Lisa
Sales Rep: Robert Cleary
Quote Number:
Called In By: Ray Veronneau
Called In Phone: 203-393-0035
Site Contact: Gary Beland
Site Contact Phone: 404-242-6014
Site Contact Cell #: -

Comments:

WO Description: Bring drum wand and stinger to pump out totes and drums.** Site is located at end of dirt road on right -
Please call Ray in route to site 203-915-6533

Job Task	Unit	Exp. Qty	Actual Qty	Exp. Num	Actual Num
a) Scope of Work: n/a Profile#: P022114016FL Item: flammable liquid	GALLON	5000	4700	-	-
b) Scope of Work: n/a Item: VAC - TRAILER	TRIP	1	-	-	-

Transport:

Driver: Andrus, Douglas P
Truck#: TA-05
Times: Leave Yard - Date 2/28 Time 9:00 Arrive Site - Date 2/28 Time 10:45
Leave Site - Date 2/28 Time Arrive Yard - Date 2/28 Time

Manifest #: 011519302JJK

Driver Comments: EST 4700 PUMP 1 1/2 MIN

All prices subject to adjustment due to market condition - Customer agrees to pay service charges of 1 1/2% per month or the highest rate allowed by law (whichever is lesser) from the due date of each invoice to date of payment. In the event customer's acct is placed for collection, customer agrees to pay all costs of collection, including reasonable attorney's fees.

Signature:

PO Number: 49390

Date: 2/28/14

Cycle Chem, Inc

550 Industrial Drive Lewisberry PA 17339 PHONE: 717-938-4700, FAX:
717-938-3301

Land Disposal Restriction Notification and Certification Form

Generator: US EPA REGION II - SUPERIOR BARREL Manifest Tracking Number: 99287
AND DRUM SITE

EPAID: NJD986630705

Manifest Document Number: 012500457JJK

The EPA hazardous wastes identified below must be treated to the applicable treatment standards set forth in 40 CFR 268.40.

EPA Waste Code Information

Manifest Line	Waste-water?	EPACodes
Page 1 Line 1	No	D018
Page 1 Line 2	No	D018
Page 1 Line 3	No	D008 (Lead non-battery subcategory)
Page 1 Line 4	No	D001 (High TOC ignitable liquids subcategory), D007, D022
Page 2 Line 1	No	D001 (High TOC ignitable liquids subcategory), D007, D022
Page 2 Line 2	No	D001 (High TOC ignitable liquids subcategory), D007, D022
Page 2 Line 3	No	D002

Underlying Hazardous Constituents

(None present unless identified below.)

Manifest Line	Constituents
---------------	--------------

I certify that all information submitted on this Land Disposal Restriction and Certification Form is accurate and complete, to the best of my knowledge and information.

Signature: 

Name: Keith Glenn

Title: Federal On-Scene Coordinator

Date: 02/27/14

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator ID Number NJD986630705		2. Page 1 of 2		3. Emergency Response Phone (800) 424-8302		4. Manifest Tracking Number 012500457 JJK							
		5. Generator's Name and Mailing Address US EPA REGION II - SUPERIOR 2890 WOODBRIDGE AVENUE + Drum Site EDISON, NJ 07026 Generator's Phone: (732) 321-4454								Generator's Site Address (if different than mailing address) 798 JACOB HARRIS LANE ELK TOWNSHIP NJ 08028					
		6. Transporter 1 Company Name CLEAN VENTURE INC.						U.S. EPA ID Number NJ0000027193							
		7. Transporter 2 Company Name						U.S. EPA ID Number							
		8. Designated Facility Name and Site Address CYCLE CHEM, INC. 550 INDUSTRIAL DRIVE LEWISBERRY, PA 17339 Facility's Phone: (717) 938-4700						U.S. EPA ID Number PA0067098822							
		9a. HM		9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))				10. Containers		11. Total Quantity		12. Unit WL/Vol.		13. Waste Codes	
GENERATOR		X		1NA3082 HAZARDOUS WASTE, LIQUID, N.O.S. (Benzene) 9 PG III ERG# 171				7 TP		1670 456 GAL		D018			
		X		2NA3082 HAZARDOUS WASTE, LIQUID, N.O.S. (Benzene) 9 PG III ERG# 171				2 DF		1410 GAL		D018			
		X		3NA3082 HAZARDOUS WASTE, LIQUID, N.O.S. (Lead) 9 PG III ERG# 171				1 TP		350 GAL		D018			
		X		4UN1992 WASTE FLAMMABLE LIQUIDS, TOXIC, N.O.S. (CHLOROFORM, CHROME) 3 (6.1) PG II ERG# 131				3 TP		750 GAL		D001 D007 D022			
14. Special Handling Instructions and Additional Information JOB#7/PAWJ/5634/9/99287 (1)WR3-J ITEM J - WASTE BENZENE CONTAMINATED LIQUID (2)WR3-J ITEM J - WASTE BENZENE CONTAMINATED LIQUID (3)WDV-U ITEM U - WASTE LEAD CONTAMINATED LIQUID (4)WR3-D ITEM D- WASTE FLAMMABLE CHLOROFORM CONTAMINATED LIQUID															
15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.															
Generator's/Offor's Printed/Typed Name Keith Green (agent for EPA) Signature [Signature] Month 02 Day 27 Year 14															
TRANSPORTER		16. International Shipments <input type="checkbox"/> Import to U.S. <input type="checkbox"/> Export from U.S. Port of entry/exit: _____ Date leaving U.S.: _____													
		17. Transporter Acknowledgment of Receipt of Materials Transporter 1 Printed/Typed Name _____ Signature _____ Month 2 Day 27 Year 14 Transporter 2 Printed/Typed Name _____ Signature _____ Month _____ Day _____ Year _____													
DESIGNATED FACILITY		18. Discrepancy 18a. Discrepancy Indication Space <input type="checkbox"/> Quantity <input type="checkbox"/> Type <input type="checkbox"/> Residue <input type="checkbox"/> Partial Rejection <input type="checkbox"/> Full Rejection Manifest Reference Number: _____ 18b. Alternate Facility (or Generator) _____ U.S. EPA ID Number _____ Facility's Phone: _____ 18c. Signature of Alternate Facility (or Generator) _____ Month _____ Day _____ Year _____													
		19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems) 1. H141 2. H141 3. H141 4. H141													
		20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a Printed/Typed Name _____ Signature _____ Month _____ Day _____ Year _____													

U.S. EPA Form 8700-22

Read all instructions before completing this form.

1. This form has been designed for use on a 12-pitch (elite) typewriter which is also compatible with standard computer printers; a firm point pen may also be used—press down hard.
2. Federal regulations require generators and transporters of hazardous waste and owners or operators of hazardous waste treatment, storage, and disposal facilities to complete this form (EPA Form 8700-22) and, if necessary, the continuation sheet (EPA Form 8700-22A) for both inter- and intrastate transportation of hazardous waste.

Public reporting burden for this collection of information is estimated to average: 30 minutes for generators, 10 minutes for transporters, and 25 minutes for owners or operators of treatment, storage, and disposal facilities. This includes time for reviewing instructions, gathering data, completing, reviewing and transmitting the form. Any correspondence regarding the PRA burden statement for the manifest must be sent to the Director of the Collection Strategies Division in EPA's Office of Information Collection at the following address: U.S. Environmental Protection Agency (2822T), 1200 Pennsylvania Ave., NW., Washington, DC 20460. Do not send the completed form to this address.

I. Instructions for Generators

Item 1. Generator's U.S. EPA Identification Number

Enter the generator's U.S. EPA twelve digit identification number, or the State generator identification number if the generator site does not have an EPA identification number.

Item 2. Page 1 of ____

Enter the total number of pages used to complete this Manifest (i.e., the first page (EPA Form 8700-22) plus the number of Continuation Sheets (EPA Form 8700-22A), if any).

Item 3. Emergency Response Phone Number

Enter a phone number for which emergency response information can be obtained in the event of an incident during transportation. The emergency response phone number must:

1. Be the number of the generator or the number of an agency or organization who is capable of and accepts responsibility for providing detailed information about the shipment;
2. Reach a phone that is monitored 24 hours a day at all times the waste is in transportation (including transportation related storage); and
3. Reach someone who is either knowledgeable of the hazardous waste being shipped and has comprehensive emergency response and spill cleanup/incident mitigation information for the material being shipped or has immediate access to a person who has that knowledge and information about the shipment.

Note: Emergency Response phone number information should only be entered in Item 3 when there is one phone number that applies to all the waste materials described in Item 9b. If a situation (e.g., consolidated shipments) arises where more than one Emergency Response phone number applies to the various wastes listed on the manifest, the phone numbers associated with each specific material should be entered after its description in Item 9b.

Item 4. Manifest Tracking Number

This unique tracking number must be pre-printed on the manifest by the forms printer.

Item 5. Generator's Mailing Address, Phone Number and Site Address

Enter the name of the generator, the mailing address to which the completed manifest signed by the designated facility should be mailed, and the generator's telephone number. Note, the telephone number (including area code) should be the normal business number for the generator, or the number where the generator or his authorized agent may be reached to provide instructions in the event the designated and/or alternate (if any) facility rejects some or all of the shipment. Also enter the physical site address from which the shipment originates only if this address is different than the mailing address.

Item 6. Transporter 1 Company Name, and U.S. EPA ID Number

Enter the company name and U.S. EPA ID number of the first transporter who will transport the waste. Vehicle or driver information may not be entered here.

Item 7. Transporter 2 Company Name and U.S. EPA ID Number

If applicable, enter the company name and U.S. EPA ID number of the second transporter who will transport the waste. Vehicle or driver information may not be entered here.

If more than two transporters are needed, use a Continuation Sheet(s) (EPA Form 8700-22A).

Item 8. Designated Facility Name, Site Address, and U.S. EPA ID Number

Enter the company name and site address of the facility designated to receive the waste listed on this manifest. Also enter the facility's phone number and the U.S. EPA twelve digit identification number of the facility.

Item 9. U.S. DOT Description (Including Proper Shipping Name, Hazard Class or Division, Identification Number, and Packing Group)

Item 9a. If the wastes identified in Item 9b consist of both hazardous and nonhazardous materials, then identify the hazardous materials by entering an "X" in this item next to the corresponding hazardous material identified in Item 9b.

Item 9b. Enter the U.S. DOT Proper Shipping Name, Hazard Class or Division, Identification Number (UN/NA) and Packing Group for each waste as identified in 49 CFR 172. Include technical name(s) and reportable quantity references, if applicable.

Note: If additional space is needed for waste descriptions, enter these additional descriptions in Item 27 on the Continuation Sheet (EPA Form 8700-22A). Also, if more than one Emergency Response phone number applies to the various wastes described in either Item 9b or Item 27, enter applicable Emergency Response phone numbers immediately following the shipping descriptions for those items.

Item 10. Containers (Number and Type)

Enter the number of containers for each waste and the appropriate abbreviation from Table I (below) for the type of container.

TABLE I.—TYPES OF CONTAINERS

BA = Burlap, cloth, paper, or plastic bags.	DT = Dump truck.
CF = Fiber or plastic boxes, cartons, cases.	DW = Wooden drums, barrels, kegs.
CM = Metal boxes, cartons, cases (including roll-offs).	HG = Hopper or gondola cars.
CW = Wooden boxes, cartons, cases.	TC = Tank cars.
CY = Cylinders.	TP = Portable tanks.
DF = Fiberboard or plastic drums, barrels, kegs.	TT = Cargo tanks (tank trucks).
DM = Metal drums, barrels, kegs.	

Item 11. Total Quantity

Enter, in designated boxes, the total quantity of waste. Round partial units to the nearest whole unit, and do not enter decimals or fractions. To the extent practical, report quantities using appropriate units of measure that will allow you to report quantities with precision. Waste quantities entered should be based on actual measurements or reasonably accurate estimates of actual quantities shipped. Container capacities are not acceptable as estimates.

Item 12. Units of Measure (Weight/Volume)

Enter, in designated boxes, the appropriate abbreviation from Table II (below) for the unit of measure.

TABLE II.—UNITS OF MEASURE

G = Gallons (liquids only).	N = Cubic Meters.
K = Kilograms.	P = Pounds.
L = Liters (liquids only).	T = Tons (2000 Pounds).
M = Metric Tons (1000 kilograms).	Y = Cubic Yards.

Note: Tons, Metric Tons, Cubic Meters, and Cubic Yards should only be reported in connection with very large bulk shipments, such as rail cars, tank trucks, or barges.

Item 13. Waste Codes

Enter up to six federal and state waste codes to describe each waste stream identified in Item 9b. State waste codes that are not redundant with federal codes must be entered here, in addition to the federal waste codes which are most representative of the properties of the waste.

Item 14. Special Handling Instructions and Additional Information

1. Generators may enter any special handling or shipment-specific information necessary for the proper management or tracking of the materials under the generator's or other handler's business processes, such as waste profile numbers, container codes, bar codes, or response guide numbers. Generators also may use this space to enter additional descriptive information about their shipped materials, such as chemical names, constituent percentages, physical state, or specific gravity of wastes identified with volume units in Item 12.
2. This space may be used to record limited types of federally required information for which there is no specific space provided on the manifest, including any alternate facility designations; the manifest tracking number of the original manifest for rejected wastes and residues that are re-shipped under a second manifest; and the specification of PCB waste descriptions and PCB out-of-service dates required under 40 CFR 761.207. Generators, however, cannot be required to enter information in this space to meet state regulatory requirements.

Item 15. Generator's/Officer's Certifications

1. The generator must read, sign, and date the waste minimization certification statement. In signing the waste minimization certification statement, those generators who have not been exempted by statute or regulation from the duty to make a waste minimization certification under section 3002(b) of RCRA are also certifying that they have complied with the waste minimization requirements. The Generator's Certification also contains the required attestation that the shipment has been properly prepared and is in proper condition for transportation (the shipper's certification). The content of the shipper's certification statement is as follows: "I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent." When a party other than the generator prepares the shipment for transportation, this party may also sign the shipper's certification statement as the offeror of the shipment.
2. Generator or Offeror personnel may preprint the words, "On behalf of" in the signature block or may hand write this statement in the signature block prior to signing the generator/offeror certification, to indicate that the individual signs as the employee or agent of the named principal.

Note: All of the above information except the handwritten signature required in Item 15 may be pre-printed.

UNIFORM HAZARDOUS WASTE MANIFEST (Continuation Sheet)		21. Generator ID Number NJ0986630703	22. Page 2 of 2	23. Manifest Tracking Number 012500457JJK		
24. Generator's Name: US EPA REGION II - SUPERIOR BARREL AND DRUM SITE 2890 WOODBRIDGE AVENUE EDISON, NJ 07026						
25. Transporter _____ Company Name				U.S. EPA ID Number		
26. Transporter _____ Company Name				U.S. EPA ID Number		
27a. HM	27b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	28. Containers No. Type		29. Total Quantity	30. Unit Wt./Vol.	31. Waste Codes
X	(1) UN1992 WASTE FLAMMABLE LIQUIDS, TOXIC, N.O.S. (CHLOROFORM, CHROME) 3 (6.1) PG II ERG# 131	1	DF	95	CHL	D001 D007 D022
X	(2) UN1992 WASTE FLAMMABLE LIQUIDS, TOXIC, N.O.S. (CHLOROFORM, CHROME) 3 (6.1) PG II ERG# 131	5	DM	425	CHL	D001 D007 D022
X	(3) UN3267 WASTE CORROSIVE LIQUID, BASIC, ORGANIC, N.O.S. (UNLISTED HAZARDOUS WASTES CHARACTERISTICS OF CORROSIVITY) 8 PG II	1	DF	95	CHL	D002
32. Special Handling Instructions and Additional Information JOB6/AWNJ/563479/99287 ERG# 153 (1)WR3-D ITEM D- WASTE FLAMMABLE CHLOROFORM CONTAMINATED LIQUID (2)WR3-D ITEM D- WASTE FLAMMABLE CHLOROFORM CONTAMINATED LIQUID (3)CXL-M ITEM M - WASTE CORROSIVE ORGANIC BASIC LIQUID						
33. Transporter _____ Acknowledgment of Receipt of Materials Printed/Typed Name Signature Month Day Year						
34. Transporter _____ Acknowledgment of Receipt of Materials Printed/Typed Name Signature Month Day Year						
35. Discrepancy						
36. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems) H141 H141 H141						

Instructions—Continuation Sheet
U.S. EPA Form 8700-22A

Read all instructions before completing this form. This form has been designed for use on a 12-pitch (elite) typewriter; a firm point pen may also be used—press down hard.

This form must be used as a continuation sheet to U.S. EPA Form 8700-22 if:

- More than two transporters are to be used to transport the waste; or
- More space is required for the U.S. DOT descriptions and related information in Item 9 of U.S. EPA Form 8700-22.

Federal regulations require generators and transporters of hazardous waste and owners or operators of hazardous waste treatment, storage, or disposal facilities to use the uniform hazardous waste manifest (EPA Form 8700-22) and, if necessary, this continuation sheet (EPA Form 8700-22A) for both interstate and intrastate transportation.

I. Instructions for Generators

Item 21. Generator's ID Number

Enter the generator's U.S. EPA twelve digit identification number or, the State generator identification number if the generator site does not have an EPA identification number.

Item 22. Page ____

Enter the page number of this Continuation Sheet.

Item 23. Manifest Tracking Number

Enter the Manifest Tracking number from Item 4 of the Manifest form to which this continuation sheet is attached.

Item 24. Generator's Name—

Enter the generator's name as it appears in Item 5 on the first page of the Manifest.

Item 25. Transporter—Company Name

If additional transporters are used to transport the waste described on this Manifest, enter the company name of each additional transporter in the order in which they will transport the waste. Enter after the word "Transporter" the order of the transporter. For example, Transporter 3 Company Name. Also enter the U.S. EPA twelve digit identification number of the transporter described in Item 25.

Item 26. Transporter—Company Name

If additional transporters are used to transport the waste described on this Manifest, enter the company name of each additional transporter in the order in which they will transport the waste. Enter after the word "Transporter" the order of the transporter. For example, Transporter 4 Company Name. Each Continuation Sheet can record the names of two additional transporters. Also enter the U.S. EPA twelve digit identification number of the transporter named in Item 26.

Item 27. U.S. D.O.T. Description Including Proper Shipping Name, Hazardous Class, and ID Number (UN/NA)

For each row enter a sequential number under Item 27b that corresponds to the order of waste codes from one continuation sheet to the next, to reflect the total number of wastes being shipped. Refer to instructions for Item 9 of the manifest for the information to be entered.

Item 28. Containers (No. And Type)

Refer to the instructions for Item 10 of the manifest for information to be entered.

Item 29. Total Quantity

Refer to the instructions for Item 11 of the manifest form.

Item 30. Units of Measure (Weight/Volume)

Refer to the instructions for Item 12 of the manifest form.

Item 31. Waste Codes

Refer to the instructions for Item 13 of the manifest form.

Item 32. Special Handling Instructions and Additional Information

Refer to the instructions for Item 14 of the manifest form.

Cycle Chem, Inc

550 Industrial Drive Lewisberry PA 17339 PHONE: 717-938-4700, FAX:
717-938-3301

Land Disposal Restriction Notification and Certification Form

Generator: US EPA REGION II - SUPERIOR BARREL Manifest Tracking Number: 99070
AND DRUM SITE

EPAID: NJD986630705

Manifest Document Number: 012500358JJK

The EPA hazardous wastes identified below must be treated to the applicable treatment standards set forth in 40 CFR 268.40.

EPA Waste Code Information

Manifest Line	Waste-water?	EPA Codes
Page 1 Line 1	No	D002
Page 1 Line 2	No	D002
Page 1 Line 3	No	D002
Page 1 Line 4	No	D002, D010
Page 2 Line 1	No	D002, D008 (Lead non-battery subcategory)
Page 2 Line 2	No	D002, D008 (Lead non-battery subcategory), D010
Page 2 Line 3	No	D002, D007, D010, D039
Page 2 Line 4	No	D002, D007, D010, D039
Page 2 Line 5	No	D002, D007, D010, D039
Page 2 Line 6	No	D010
Page 2 Line 7	No	D010
Page 2 Line 8	No	D002

Underlying Hazardous Constituents

(None present unless identified below.)

Manifest Line	Constituents
---------------	--------------

I certify that all information submitted on this Land Disposal Restriction and Certification Form is accurate and complete, to the best of my knowledge and information.

Signature: _____

Name: _____

Title: _____

Date: _____

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator ID Number NJD986630705		2. Page 1 of 2	3. Emergency Response Phone (800) 424-8802		4. Manifest Tracking Number 012500358 JJK		
		5. Generator's Name and Mailing Address US EPA REGION II - SUPERIOR 2890 WOODBRIDGE AVENUE Edison NJ 07026 798 JACOB HARRIS LANE ELK TOWNSHIP NJ 08028							
6. Transporter 1 Company Name CLEAN VENTURE INC.		U.S. EPA ID Number NJ0000027193		7. Transporter 2 Company Name					
8. Designated Facility Name and Site Address CYCLE CHEM, INC. 550 INDUSTRIAL DRIVE LEWISBERRY, PA 17339 Facility's Phone: (717) 938-4700		U.S. EPA ID Number PA0067098822							
GENERATOR	9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	10. Containers No.	Type	11. Total Quantity	12. Unit WL/Vol.	13. Waste Codes		
	X	1. UN3266 WASTE CORROSIVE LIQUID, BASIC, INORGANIC, N.O.S. (UNLISTED HAZARDOUS WASTES CHARACTERISTICS OF CORROSIVITY) 8 PG II	7	DF	165 GALL		D002		
	X	2. UN3266 WASTE CORROSIVE LIQUID, BASIC, INORGANIC, N.O.S. (UNLISTED HAZARDOUS WASTES CHARACTERISTICS OF CORROSIVITY) 8 PG II	2	TP	500 GALL		D002		
	X	3. UN3266 WASTE CORROSIVE LIQUID, BASIC, INORGANIC, N.O.S. (UNLISTED HAZARDOUS WASTES CHARACTERISTICS OF CORROSIVITY) 8 PG II	14	TP	1111 GALL		D002		
	X	4. UN3266 WASTE CORROSIVE LIQUID, BASIC, INORGANIC, N.O.S. (UNLISTED HAZARDOUS WASTES CHARACTERISTICS OF CORROSIVITY, SELENIUM) 8 PG II	2	DF	192 GALL		D002 D010		
14. Special Handling Instructions and Additional Information JOBS/AWNJ/563254/99070 ;ERG# 154 ;ERG# 154 ;ERG# 154 ;ERG# 154 (1)WDV-B ITEM B - WASTE CORROSIVE INORGANIC BASIC LIQUID (2)WDV-B ITEM B - WASTE CORROSIVE INORGANIC BASIC LIQUID (3)WDV-B ITEM B - WASTE CORROSIVE INORGANIC BASIC LIQUID (4)WDV-E ITEM E - WASTE SELENIUM CONTAMINATED CORROSIVE INORGANIC BASIC LIQUID									
15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.									
Generator's/Offor's Printed/Typed Name Kathi Glavin for USEPA		Signature <i>[Signature]</i>		Month 02		Day 20		Year 14	
INT'L	16. International Shipments <input type="checkbox"/> Import to U.S. <input type="checkbox"/> Export from U.S.		Port of entry/exit: _____ Date leaving U.S.: _____						
	17. Transporter Acknowledgment of Receipt of Materials Transporter 1 Printed/Typed Name Emilio Rivera Signature <i>[Signature]</i> Month 02 Day 20 Year 14 Transporter 2 Printed/Typed Name _____ Signature _____ Month _____ Day _____ Year _____								
DESIGNATED FACILITY	18. Discrepancy 18a. Discrepancy Indication Space <input type="checkbox"/> Quantity <input type="checkbox"/> Type <input type="checkbox"/> Residue <input type="checkbox"/> Partial Rejection <input type="checkbox"/> Full Rejection Manifest Reference Number: _____ U.S. EPA ID Number _____								
	18b. Alternate Facility (or Generator) _____ U.S. EPA ID Number _____ Facility's Phone: _____								
	18c. Signature of Alternate Facility (or Generator) _____ Month _____ Day _____ Year _____								
	19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems) 1. H141 2. H141 3. H141 4. H141								
20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a Printed/Typed Name _____ Signature _____ Month _____ Day _____ Year _____									

U.S. EPA Form 8700-22

Read all instructions before completing this form.

1. This form has been designed for use on a 12-pitch (elite) typewriter which is also compatible with standard computer printers; a firm point pen may also be used—press down hard.
2. Federal regulations require generators and transporters of hazardous waste and owners or operators of hazardous waste treatment, storage, and disposal facilities to complete this form (EPA Form 8700-22) and, if necessary, the continuation sheet (EPA Form 8700-22A) for both inter- and intrastate transportation of hazardous waste.

Public reporting burden for this collection of information is estimated to average: 30 minutes for generators, 10 minutes for transporters, and 25 minutes for owners or operators of treatment, storage, and disposal facilities. This includes time for reviewing instructions, gathering data, completing, reviewing and transmitting the form. Any correspondence regarding the PRA burden statement for the manifest must be sent to the Director of the Collection Strategies Division in EPA's Office of Information Collection at the following address: U.S. Environmental Protection Agency (2822T), 1200 Pennsylvania Ave., NW., Washington, DC 20460. Do not send the completed form to this address.

I. Instructions for Generators

Item 1. Generator's U.S. EPA Identification Number

Enter the generator's U.S. EPA twelve digit identification number, or the State generator identification number if the generator site does not have an EPA identification number.

Item 2. Page 1 of ____

Enter the total number of pages used to complete this Manifest (i.e., the first page (EPA Form 8700-22) plus the number of Continuation Sheets (EPA Form 8700-22A), if any).

Item 3. Emergency Response Phone Number

Enter a phone number for which emergency response information can be obtained in the event of an incident during transportation. The emergency response phone number must:

1. Be the number of the generator or the number of an agency or organization who is capable of and accepts responsibility for providing detailed information about the shipment;
2. Reach a phone that is monitored 24 hours a day at all times the waste is in transportation (including transportation related storage); and
3. Reach someone who is either knowledgeable of the hazardous waste being shipped and has comprehensive emergency response and spill cleanup/incident mitigation information for the material being shipped or has immediate access to a person who has that knowledge and information about the shipment.

Note: Emergency Response phone number information should only be entered in Item 3 when there is one phone number that applies to all the waste materials described in Item 9b. If a situation (e.g., consolidated shipments) arises where more than one Emergency Response phone number applies to the various wastes listed on the manifest, the phone numbers associated with each specific material should be entered after its description in Item 9b.

Item 4. Manifest Tracking Number

This unique tracking number must be pre-printed on the manifest by the forms printer.

Item 5. Generator's Mailing Address, Phone Number and Site Address

Enter the name of the generator, the mailing address to which the completed manifest signed by the designated facility should be mailed, and the generator's telephone number. Note, the telephone number (including area code) should be the normal business number for the generator, or the number where the generator or his authorized agent may be reached to provide instructions in the event the designated and/or alternate (if any) facility rejects some or all of the shipment. Also enter the physical site address from which the shipment originates only if this address is different than the mailing address.

Item 6. Transporter 1 Company Name, and U.S. EPA ID Number

Enter the company name and U.S. EPA ID number of the first transporter who will transport the waste. Vehicle or driver information may not be entered here.

Item 7. Transporter 2 Company Name and U.S. EPA ID Number

If applicable, enter the company name and U.S. EPA ID number of the second transporter who will transport the waste. Vehicle or driver information may not be entered here.

If more than two transporters are needed, use a Continuation Sheet(s) (EPA Form 8700-22A).

Item 8. Designated Facility Name, Site Address, and U.S. EPA ID Number

Enter the company name and site address of the facility designated to receive the waste listed on this manifest. Also enter the facility's phone number and the U.S. EPA twelve digit identification number of the facility.

Item 9. U.S. DOT Description (Including Proper Shipping Name, Hazard Class or Division, Identification Number, and Packing Group)

Item 9a. If the wastes identified in Item 9b consist of both hazardous and nonhazardous materials, then identify the hazardous materials by entering an "X" in this Item next to the corresponding hazardous material identified in Item 9b.

Item 9b. Enter the U.S. DOT Proper Shipping Name, Hazard Class or Division, Identification Number (UN/NA) and Packing Group for each waste as identified in 49 CFR 172. Include technical name(s) and reportable quantity references, if applicable.

Note: If additional space is needed for waste descriptions, enter these additional descriptions in Item 27 on the Continuation Sheet (EPA Form 8700-22A). Also, if more than one Emergency Response phone number applies to the various wastes described in either Item 9b or Item 27, enter applicable Emergency Response phone numbers immediately following the shipping descriptions for those items.

Item 10. Containers (Number and Type)

Enter the number of containers for each waste and the appropriate abbreviation from Table I (below) for the type of container.

TABLE I.—TYPES OF CONTAINERS

BA = Burlap, cloth, paper, or plastic bags.	DT = Dump truck.
CF = Fiber or plastic boxes, cartons, cases.	DW = Wooden drums, barrels, kegs.
CM = Metal boxes, cartons, cases (including roll-offs).	HG = Hopper or gondola cars.
CW = Wooden boxes, cartons, cases.	TC = Tank cars.
CY = Cylinders.	TP = Portable tanks.
DF = Fiberboard or plastic drums, barrels, kegs.	TT = Cargo tanks (tank trucks).
DM = Metal drums, barrels, kegs.	

Item 11. Total Quantity

Enter, in designated boxes, the total quantity of waste. Round partial units to the nearest whole unit, and do not enter decimals or fractions. To the extent practical, report quantities using appropriate units of measure that will allow you to report quantities with precision. Waste quantities entered should be based on actual measurements or reasonably accurate estimates of actual quantities shipped. Container capacities are not acceptable as estimates.

Item 12. Units of Measure (Weight/Volume)

Enter, in designated boxes, the appropriate abbreviation from Table II (below) for the unit of measure.

TABLE II.—UNITS OF MEASURE

G = Gallons (liquids only).	N = Cubic Meters.
K = Kilograms.	P = Pounds.
L = Liters (liquids only).	T = Tons (2000 Pounds).
M = Metric Tons (1000 kilograms).	Y = Cubic Yards.

Note: Tons, Metric Tons, Cubic Meters, and Cubic Yards should only be reported in connection with very large bulk shipments, such as rail cars, tank trucks, or barges.

Item 13. Waste Codes

Enter up to six federal and state waste codes to describe each waste stream identified in Item 9b. State waste codes that are not redundant with federal codes must be entered here, in addition to the federal waste codes which are most representative of the properties of the waste.

Item 14. Special Handling Instructions and Additional Information

1. Generators may enter any special handling or shipment-specific information necessary for the proper management or tracking of the materials under the generator's or other handler's business processes, such as waste profile numbers, container codes, bar codes, or response guide numbers. Generators also may use this space to enter additional descriptive information about their shipped materials, such as chemical names, constituent percentages, physical state, or specific gravity of wastes identified with volume units in Item 12.
2. This space may be used to record limited types of federally required information for which there is no specific space provided on the manifest, including any alternate facility designations; the manifest tracking number of the original manifest for rejected wastes and residues that are re-shipped under a second manifest; and the specification of PCB waste descriptions and PCB out-of-service dates required under 40 CFR 761.207. Generators, however, cannot be required to enter information in this space to meet state regulatory requirements.

Item 15. Generator's/Officer's Certifications

1. The generator must read, sign, and date the waste minimization certification statement. In signing the waste minimization certification statement, those generators who have not been exempted by statute or regulation from the duty to make a waste minimization certification under section 3002(b) of RCRA are also certifying that they have complied with the waste minimization requirements. The Generator's Certification also contains the required attestation that the shipment has been properly prepared and is in proper condition for transportation (the shipper's certification). The content of the shipper's certification statement is as follows: "I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent." When a party other than the generator prepares the shipment for transportation, this party may also sign the shipper's certification statement as the offeror of the shipment.
2. Generator or Offeror personnel may preprint the words, "On behalf of" in the signature block or may hand write this statement in the signature block prior to signing the generator/offeror certification, to indicate that the individual signs as the employee or agent of the named principal.

Note: All of the above information except the handwritten signature required in Item 15 may be pre-printed.

UNIFORM HAZARDOUS WASTE MANIFEST (Continuation Sheet)		21. Generator ID Number NJ0986630705	22. Page 2 of 2	23. Manifest Tracking Number 012500358JJK		
24. Generator's Name US EPA REGION II - SUPERIOR BARREL AND DRUM SITE 2890 WOODBRIDGE AVENUE EDISON, NJ 07026						
25. Transporter _____ Company Name				U.S. EPA ID Number		
26. Transporter _____ Company Name				U.S. EPA ID Number		
27a. HM	27b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	28. Containers		29. Total Quantity	30. Unit Wt./Vol.	31. Waste Codes
		No.	Type			
X	(1) UN3265 WASTE CORROSIVE LIQUID, BASIC, INORGANIC, N.O.S. (UNLISTED HAZARDOUS WASTES CHARACTERISTICS OF CORROSIVITY, LEAD) 8 PG II	5	DF	475 GAL		D002 D008
X	(2) UN3265 WASTE CORROSIVE LIQUID, BASIC, INORGANIC, N.O.S. (UNLISTED HAZARDOUS WASTES CHARACTERISTICS OF CORROSIVITY, LEAD) 8 PG II	2	DF	140 GAL		D002 D008 D010
X	(3) UN3265 WASTE CORROSIVE LIQUID, BASIC, INORGANIC, N.O.S. (UNLISTED HAZARDOUS WASTES CHARACTERISTICS OF CORROSIVITY) 8 PG II	3	DF	225 GAL		D002 D007 D010 D039
X	(4) UN3265 WASTE CORROSIVE LIQUID, BASIC, INORGANIC, N.O.S. (UNLISTED HAZARDOUS WASTES CHARACTERISTICS OF CORROSIVITY) 8 PG II	1	TP	300 GAL		D002 D007 D010 D039
X	(5) UN3265 WASTE CORROSIVE LIQUID, BASIC, INORGANIC, N.O.S. (UNLISTED HAZARDOUS WASTES CHARACTERISTICS OF CORROSIVITY) 8 PG II	3	TP	450 GAL		D002 D007 D010 D039
X	(6) NA3082 HAZARDOUS WASTE, LIQUID, N.O.S. (Selenium) 9 PG III ER6# 171	3	DF	375 GAL		D010
X	(7) NA3082 HAZARDOUS WASTE, LIQUID, N.O.S. (Selenium) 9 PG III ER6# 171	4	TP	1000 GAL		D010
X	(8) UN3267 WASTE CORROSIVE LIQUID, BASIC, ORGANIC, N.O.S. (UNLISTED HAZARDOUS WASTES CHARACTERISTICS OF CORROSIVITY) 8 PG II	3	DF	225 GAL		D002
32. Special Handling Instructions and Additional Information J026/ANNJ/365254/95070 ;ER6# 154 ;ER6# 154 ;ER6# 154 ;ER6# 154 ;ER6# 154 ;ER6# 154 ;ER6# 154 (1)WDV-F ITEM F - WASTE LEA (2)WDV-G ITEM G - WASTE LEAD AND SELENIUM (3)WDV-H ITEM H - WASTE CHROMIUM AND SELENIU (4)WDV-H ITEM H - WASTE CHROMIUM AND SELENIU (5)WDV-H ITEM H - WASTE CHROMIUM AND SELENIU (6)WDV-I ITEM I (7)WDV-I ITEM I						
33. Transporter _____ Acknowledgment of Receipt of Materials		Printed/Typed Name		Signature		Year
34. Transporter _____ Acknowledgment of Receipt of Materials		Printed/Typed Name		Signature		Year
35. Discrepancy						
36. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)						
H141		H141		H141		H141
H141		H141		H141		

(8) is line
item K in
Subcontract 1

Instructions—Continuation Sheet
U.S. EPA Form 8700-22A

Read all instructions before completing this form. This form has been designed for use on a 12-pitch (elite) typewriter; a firm point pen may also be used—press down hard.

This form must be used as a continuation sheet to U.S. EPA Form 8700-22 if:

- More than two transporters are to be used to transport the waste; or
- More space is required for the U.S. DOT descriptions and related information in Item 9 of U.S. EPA Form 8700-22.

Federal regulations require generators and transporters of hazardous waste and owners or operators of hazardous waste treatment, storage, or disposal facilities to use the uniform hazardous waste manifest (EPA Form 8700-22) and, if necessary, this continuation sheet (EPA Form 8700-22A) for both interstate and intrastate transportation.

I. Instructions for Generators

Item 21. Generator's ID Number

Enter the generator's U.S. EPA twelve digit identification number or, the State generator identification number if the generator site does not have an EPA identification number.

Item 22. Page ____

Enter the page number of this Continuation Sheet.

Item 23. Manifest Tracking Number

Enter the Manifest Tracking number from Item 4 of the Manifest form to which this continuation sheet is attached.

Item 24. Generator's Name—

Enter the generator's name as it appears in Item 5 on the first page of the Manifest.

Item 25. Transporter—Company Name

If additional transporters are used to transport the waste described on this Manifest, enter the company name of each additional transporter in the order in which they will transport the waste. Enter after the word "Transporter" the order of the transporter. For example, Transporter 3 Company Name. Also enter the U.S. EPA twelve digit identification number of the transporter described in Item 25.

Item 26. Transporter—Company Name

If additional transporters are used to transport the waste described on this Manifest, enter the company name of each additional transporter in the order in which they will transport the waste. Enter after the word "Transporter" the order of the transporter. For example, Transporter 4 Company Name. Each Continuation Sheet can record the names of two additional transporters. Also enter the U.S. EPA twelve digit identification number of the transporter named in Item 26.

Item 27. U.S. D.O.T. Description Including Proper Shipping Name, Hazardous Class, and ID Number (UN/NA)

For each row enter a sequential number under Item 27b that corresponds to the order of waste codes from one continuation sheet to the next, to reflect the total number of wastes being shipped. Refer to instructions for Item 9 of the manifest for the information to be entered.

Item 28. Containers (No. And Type)

Refer to the instructions for Item 10 of the manifest for information to be entered.

Item 29. Total Quantity

Refer to the instructions for Item 11 of the manifest form.

Item 30. Units of Measure (Weight/Volume)

Refer to the instructions for Item 12 of the manifest form.

Item 31. Waste Codes

Refer to the instructions for Item 13 of the manifest form.

Item 32. Special Handling Instructions and Additional Information

Refer to the instructions for Item 14 of the manifest form.

MANIFESTS

Cycle Chem, Inc

Industrial Drive Lewisberry PA 17339 PHONE: 717-938-4700, FAX: 717-938-3301

Land Disposal Restriction Notification and Certification Form

Generator: US EPA REGION II - SUPERIOR BARREL Manifest Tracking Number: 98727
AND DRUM SITE

EPAID: NJD986630705

Manifest Document Number: 012500266JJK

The EPA hazardous wastes identified below must be treated to the applicable treatment standards set forth in 40 CFR 268.40.

EPA Waste Code Information

Manifest Line	Waste-water?	EPA Codes
Page 1 Line 1	No	D001 (Ignitable characteristic wastes subcategory, other than high TOC ignitable liquids)
Page 1 Line 2	No	D001 (Ignitable characteristic wastes subcategory, other than high TOC ignitable liquids)
Page 1 Line 3	No	D001 (Ignitable characteristic wastes subcategory, other than high TOC ignitable liquids), D009 (Low mercury [<260 PPM total mercury] subcategory)
Page 1 Line 4	No	D002
Page 2 Line 1	No	D002
Page 2 Line 2	No	D002
Page 2 Line 3	No	D007, D008 (Lead non-battery subcategory)
Page 2 Line 4	No	D007, D008 (Lead non-battery subcategory)
Page 2 Line 5	No	D002, D009 (Low mercury [<260 PPM total mercury] subcategory)
Page 2 Line 6	No	D002
Page 2 Line 7	No	D002
Page 2 Line 8	No	D002
Page 2 Line 9	No	D001 (High TOC ignitable liquids subcategory), D035
Page 2 Line 10	No	D001 (High TOC ignitable liquids subcategory), D035
Page 3 Line 1	No	D001 (High TOC ignitable liquids subcategory), D008 (Lead non-battery subcategory), D035, D039
Page 3 Line 2	No	D001 (High TOC ignitable liquids subcategory), D008 (Lead non-battery subcategory), D035, D039

Underlying Hazardous Constituents

(None present unless identified below.)

Manifest Line	Constituents
---------------	--------------

I certify that all information submitted On this Land Disposal Restriction and Certification Form is accurate and complete, to the best of my knowledge and information.

Signature: Margaret Gregor

Name: Margaret Gregor

Title: On-Scene Coordinator

Date: 02/06/2014

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator ID Number	2. Page 1 of	3. Emergency Response Phone	4. Manifest Tracking Number			
		NJD986630705	3	(800) 424-8802	012500266 JJK			
5. Generator's Name and Mailing Address US EPA REGION II - SUPERIOR 2890 WOODBRIDGE AVENUE EDISON, NJ 07026								
Generator's Site Address (if different than mailing address) 798 JACOB HARRIS LANE ELK TOWNSHIP NJ 08028								
6. Transporter 1 Company Name U.S. EPA ID Number								
7. Transporter 2 Company Name U.S. EPA ID Number								
8. Designated Facility Name and Site Address CYCLE CHEM, INC. 350 INDUSTRIAL DRIVE LEWISBERRY, PA 17339 Facility's Phone: (717) 938-4700 U.S. EPA ID Number PA0067098022								
GENERATOR	9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	10. Containers No. Type		11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes	
	X	1. UN2925 WASTE FLAMMABLE SOLIDS, CORROSIVE, ORGANIC, N.O.S. (UNLISTED HAZARDOUS WASTES CHARACTERISTICS OF IGNITABILITY) 4.1 (8) PG II	4	DF	147	P	D001	
	X	2. UN2925 WASTE FLAMMABLE SOLIDS, CORROSIVE, ORGANIC, N.O.S. (UNLISTED HAZARDOUS WASTES CHARACTERISTICS OF IGNITABILITY) 4.1 (8) PG II	3	TP	902	P	D001	
	X	3. UN3180 WASTE FLAMMABLE SOLID, CORROSIVE, INORGANIC, N.O.S. (UNLISTED HAZARDOUS WASTES CHARACTERISTICS OF IGNITABILITY, Mercury) 4.1	1	DM	50	P	D001	D003
	X	4. UN3264 WASTE CORROSIVE LIQUID, ACIDIC, INORGANIC, N.O.S. (UNLISTED HAZARDOUS WASTES CHARACTERISTICS OF CORROSIVITY) 8 PG II	1	DF	15	G	D002	
14. Special Handling Instructions and Additional Information JOBG/AWN/J/562847/98727 ;ERG# 134 ;ERG# 134 ;ERG# 134 ;ERG# 154 (1)SSM-L ITEM L - WASTE FLAMMABLE SOLID (2)SSM-L ITEM L - WASTE FLAMMABLE SOLID (3)SSM-O ITEM O - WASTE FLAMMABLE CORROSIVE ACIDIC SOLID (4)CIB-P ITEM P - WASTE CORROSIVE INORGANIC ACIDIC LIQUID								
15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.								
Generator's/Offor's Printed/Typed Name Margaret Grigor								
Signature Margaret Grigor								
Month Day Year 02 06 14								
INTL	16. International Shipments <input type="checkbox"/> Import to U.S. <input type="checkbox"/> Export from U.S. Port of entry/exit: Date leaving U.S.:							
	Transporter signature (for exports only):							
TRANSPORTER	17. Transporter Acknowledgment of Receipt of Materials							
	Transporter 1 Printed/Typed Name Kenneth L. Mottet Jr.							
Signature Kenneth L. Mottet Jr.								
Month Day Year 02 06 14								
DESIGNATED FACILITY	18. Discrepancy							
	18a. Discrepancy Indication Space <input type="checkbox"/> Quantity <input type="checkbox"/> Type <input type="checkbox"/> Residue <input type="checkbox"/> Partial Rejection <input type="checkbox"/> Full Rejection							
	Manifest Reference Number:							
	18b. Alternate Facility (or Generator) U.S. EPA ID Number							
	Facility's Phone:							
18c. Signature of Alternate Facility (or Generator) Month Day Year								
19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)								
1. H141		2. H141		3. H141		4. H141		
20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a								
Printed/Typed Name Signature Month Day Year								

U.S. EPA Form 8700-22

Read all instructions before completing this form.

1. This form has been designed for use on a 12-pitch (elite) typewriter which is also compatible with standard computer printers; a firm point pen may also be used—press down hard.
2. Federal regulations require generators and transporters of hazardous waste and owners or operators of hazardous waste treatment, storage, and disposal facilities to complete this form (EPA Form 8700-22) and, if necessary, the continuation sheet (EPA Form 8700-22A) for both inter- and intrastate transportation of hazardous waste.

Public reporting burden for this collection of information is estimated to average: 30 minutes for generators, 10 minutes for transporters, and 25 minutes for owners or operators of treatment, storage, and disposal facilities. This includes time for reviewing instructions, gathering data, completing, reviewing and transmitting the form. Any correspondence regarding the PRA burden statement for the manifest must be sent to the Director of the Collection Strategies Division in EPA's Office of Information Collection at the following address: U.S. Environmental Protection Agency (2822T), 1200 Pennsylvania Ave., NW., Washington, DC 20460. Do not send the completed form to this address.

I. Instructions for Generators

Item 1. Generator's U.S. EPA Identification Number

Enter the generator's U.S. EPA twelve digit identification number, or the State generator identification number if the generator site does not have an EPA identification number.

Item 2. Page 1 of ____

Enter the total number of pages used to complete this Manifest (i.e., the first page (EPA Form 8700-22) plus the number of Continuation Sheets (EPA Form 8700-22A), if any).

Item 3. Emergency Response Phone Number

Enter a phone number for which emergency response information can be obtained in the event of an incident during transportation. The emergency response phone number must:

1. Be the number of the generator or the number of an agency or organization who is capable of and accepts responsibility for providing detailed information about the shipment;
2. Reach a phone that is monitored 24 hours a day at all times the waste is in transportation (including transportation related storage); and
3. Reach someone who is either knowledgeable of the hazardous waste being shipped and has comprehensive emergency response and spill cleanup/incident mitigation information for the material being shipped or has immediate access to a person who has that knowledge and information about the shipment.

Note: Emergency Response phone number information should only be entered in Item 3 when there is one phone number that applies to all the waste materials described in Item 9b. If a situation (e.g., consolidated shipments) arises where more than one Emergency Response phone number applies to the various wastes listed on the manifest, the phone numbers associated with each specific material should be entered after its description in Item 9b.

Item 4. Manifest Tracking Number

This unique tracking number must be pre-printed on the manifest by the forms printer.

Item 5. Generator's Mailing Address, Phone Number and Site Address

Enter the name of the generator, the mailing address to which the completed manifest signed by the designated facility should be mailed, and the generator's telephone number. Note, the telephone number (including area code) should be the normal business number for the generator, or the number where the generator or his authorized agent may be reached to provide instructions in the event the designated and/or alternate (if any) facility rejects some or all of the shipment. Also enter the physical site address from which the shipment originates only if this address is different than the mailing address.

Item 6. Transporter 1 Company Name, and U.S. EPA ID Number

Enter the company name and U.S. EPA ID number of the first transporter who will transport the waste. Vehicle or driver information may not be entered here.

Item 7. Transporter 2 Company Name and U.S. EPA ID Number

If applicable, enter the company name and U.S. EPA ID number of the second transporter who will transport the waste. Vehicle or driver information may not be entered here.

If more than two transporters are needed, use a Continuation Sheet(s) (EPA Form 8700-22A).

Item 8. Designated Facility Name, Site Address, and U.S. EPA ID Number

Enter the company name and site address of the facility designated to receive the waste listed on this manifest. Also enter the facility's phone number and the U.S. EPA twelve digit identification number of the facility.

Item 9. U.S. DOT Description (Including Proper Shipping Name, Hazard Class or Division, Identification Number, and Packing Group)

Item 9a. If the wastes identified in Item 9b consist of both hazardous and nonhazardous materials, then identify the hazardous materials by entering an "X" in this Item next to the corresponding hazardous material identified in Item 9b.

Item 9b. Enter the U.S. DOT Proper Shipping Name, Hazard Class or Division, Identification Number (UN/NA) and Packing Group for each waste as identified in 49 CFR 172. Include technical name(s) and reportable quantity references, if applicable.

Note: If additional space is needed for waste descriptions, enter these additional descriptions in Item 27 on the Continuation Sheet (EPA Form 8700-22A). Also, if more than one Emergency Response phone number applies to the various wastes described in either Item 9b or Item 27, enter applicable Emergency Response phone numbers immediately following the shipping descriptions for those items.

Item 10. Containers (Number and Type)

Enter the number of containers for each waste and the appropriate abbreviation from Table I (below) for the type of container.

TABLE I.—TYPES OF CONTAINERS

BA = Burlap, cloth, paper, or plastic bags.	DT = Dump truck.
CF = Fiber or plastic boxes, cartons, cases.	DW = Wooden drums, barrels, kegs.
CM = Metal boxes, cartons, cases (including roll-offs).	HG = Hopper or gondola cars.
CW = Wooden boxes, cartons, cases.	TC = Tank cars.
CY = Cylinders.	TP = Portable tanks.
DF = Fiberboard or plastic drums, barrels, kegs.	TT = Cargo tanks (tank trucks).
DM = Metal drums, barrels, kegs.	

Item 11. Total Quantity

Enter, in designated boxes, the total quantity of waste. Round partial units to the nearest whole unit, and *do not* enter decimals or fractions. To the extent practical, report quantities using appropriate units of measure that will allow you to report quantities with precision. Waste quantities entered should be based on actual measurements or reasonably accurate estimates of actual quantities shipped. Container capacities are not acceptable as estimates.

Item 12. Units of Measure (Weight/Volume)

Enter, in designated boxes, the appropriate abbreviation from Table II (below) for the unit of measure.

TABLE II.—UNITS OF MEASURE

G = Gallons (liquids only).	N = Cubic Meters.
K = Kilograms.	P = Pounds.
L = Liters (liquids only).	T = Tons (2000 Pounds).
M = Metric Tons (1000 kilograms).	Y = Cubic Yards.

Note: Tons, Metric Tons, Cubic Meters, and Cubic Yards should only be reported in connection with very large bulk shipments, such as rail cars, tank trucks, or barges.

Item 13. Waste Codes

Enter up to six federal and state waste codes to describe each waste stream identified in Item 9b. State waste codes that are not redundant with federal codes must be entered here, in addition to the federal waste codes which are most representative of the properties of the waste.

Item 14. Special Handling Instructions and Additional Information

1. Generators may enter any special handling or shipment-specific information necessary for the proper management or tracking of the materials under the generator's or other handler's business processes, such as waste profile numbers, container codes, bar codes, or response guide numbers. Generators also may use this space to enter additional descriptive information about their shipped materials, such as chemical names, constituent percentages, physical state, or specific gravity of wastes identified with volume units in Item 12.
2. This space may be used to record limited types of federally required information for which there is no specific space provided on the manifest, including any alternate facility designations; the manifest tracking number of the original manifest for rejected wastes and residues that are re-shipped under a second manifest; and the specification of PCB waste descriptions and PCB out-of-service dates required under 40 CFR 761.207. Generators, however, cannot be required to enter information in this space to meet state regulatory requirements.

Item 15. Generator's/Officer's Certifications

1. The generator must read, sign, and date the waste minimization certification statement. In signing the waste minimization certification statement, those generators who have not been exempted by statute or regulation from the duty to make a waste minimization certification under section 3002(b) of RCRA are also certifying that they have complied with the waste minimization requirements. The Generator's Certification also contains the required attestation that the shipment has been properly prepared and is in proper condition for transportation (the shipper's certification). The content of the shipper's certification statement is as follows: "I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent." When a party other than the generator prepares the shipment for transportation, this party may also sign the shipper's certification statement as the offeror of the shipment.
2. Generator or Offeror personnel may preprint the words, "On behalf of" in the signature block or may hand write this statement in the signature block prior to signing the generator/offeror certification, to indicate that the individual signs as the employee or agent of the named principal.

Note: All of the above information except the handwritten signature required in Item 15 may be pre-printed.

UNIFORM HAZARDOUS WASTE MANIFEST (Continuation Sheet)		21. Generator ID Number NID906530705	22. Page 2 of 3	23. Manifest Tracking Number 012300266JJK	
24. Generator's Name US EPA REGION II - SUPERIOR BARREL AND DRUM SITE 2890 WOODBRIDGE AVENUE EDISON, NJ 07026					
25. Transporter _____ Company Name				U.S. EPA ID Number	
26. Transporter _____ Company Name				U.S. EPA ID Number	
27a. HM	27b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	28. Containers No. Type		29. Total Quantity	30. Unit Wt./Vol.
X	(1) UN3264 WASTE CORROSIVE LIQUID, ACIDIC, INORGANIC, N.O.S. (UNLISTED HAZARDOUS WASTES CHARACTERISTICS OF CORROSIVITY) 8 PG II	1	DM	75	D002
X	(2) UN3264 WASTE CORROSIVE LIQUID, ACIDIC, INORGANIC, N.O.S. (UNLISTED HAZARDOUS WASTES CHARACTERISTICS OF CORROSIVITY) 8 PG II	7	DF	65	D002
X	(3) NA3077 HAZARDOUS WASTE, SOLID, N.O.S. (Lead, Chromium) 9 PG III ERG# 171	8	DM	60	D007 D008
X	(4) NA3077 HAZARDOUS WASTE, SOLID, N.O.S. (Lead, Chromium) 9 PG III ERG# 171	2	DF	60	D007 D008
X	(5) UN3264 WASTE CORROSIVE LIQUID, ACIDIC, INORGANIC, N.O.S. (UNLISTED HAZARDOUS WASTES CHARACTERISTICS OF CORROSIVITY, Mercury) 8 PG II	3	DF	35	D002 D009
X	(6) UN3265 WASTE CORROSIVE LIQUID, ACIDIC, ORGANIC, N.O.S. (UNLISTED HAZARDOUS WASTES CHARACTERISTICS OF CORROSIVITY) 8 PG II	1	DM	25	D002
X	(7) UN3265 WASTE CORROSIVE LIQUID, ACIDIC, ORGANIC, N.O.S. (UNLISTED HAZARDOUS WASTES CHARACTERISTICS OF CORROSIVITY) 8 PG II	1	DF	15	D002
X	(8) UN3265 WASTE CORROSIVE LIQUID, ACIDIC, ORGANIC, N.O.S. (UNLISTED HAZARDOUS WASTES CHARACTERISTICS OF CORROSIVITY) 8 PG II	1	DM	25	D002
X	(9) UN1992 WASTE FLAMMABLE LIQUIDS, TOXIC, N.O.S. (Methyl Ethyl Ketone) 3 (6.1) PG II ERG# 131	2	DM	60	D001 D035
X	(10) UN1992 WASTE FLAMMABLE LIQUIDS, TOXIC, N.O.S. (Methyl Ethyl Ketone) 3 (6.1) PG II ERG# 131	1	DF	95	D001 D035
32. Special Handling Instructions and Additional Information JOBB/AWNJ/562847/98727 ;ERG# 154 ;ERG# 154 ;ERG# 154 ;ERG# 153 ;ERG# 153 ;ERG# 153 (1)CIB-P ITEM P - WAS (2)CIB-P ITEM P - WAS (3)LJES-Q ITEM Q - WASTE (4)LJES-Q ITEM Q - WASTE (5)CIB-R ITEM R - WASTE MERCURY CONTAMINAT (6)CIB-S ITEM S - W (7)CIA-S ITEM S - W (8)COA-T ITEM T - (9)SSM-V ITEM V - WAST (10)SSM-V ITEM V - WAST					
33. Transporter Acknowledgment of Receipt of Materials Printed/Typed Name _____ Signature _____ Month _____ Day _____ Year _____					
34. Transporter Acknowledgment of Receipt of Materials Printed/Typed Name _____ Signature _____ Month _____ Day _____ Year _____					
35. Discrepancy					
36. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)					
H141		H141		H141	
H141		H141		H141	

Instructions—Continuation Sheet
U.S. EPA Form 8700-22A

Read all instructions before completing this form. This form has been designed for use on a 12-pitch (elite) typewriter; a firm point pen may also be used—press down hard.

This form must be used as a continuation sheet to U.S. EPA Form 8700-22 if:

- More than two transporters are to be used to transport the waste; or
- More space is required for the U.S. DOT descriptions and related information in Item 9 of U.S. EPA Form 8700-22.

Federal regulations require generators and transporters of hazardous waste and owners or operators of hazardous waste treatment, storage, or disposal facilities to use the uniform hazardous waste manifest (EPA Form 8700-22) and, if necessary, this continuation sheet (EPA Form 8700-22A) for both interstate and intrastate transportation.

I. Instructions for Generators

Item 21. Generator's ID Number

Enter the generator's U.S. EPA twelve digit identification number or, the State generator identification number if the generator site does not have an EPA identification number.

Item 22. Page ____

Enter the page number of this Continuation Sheet.

Item 23. Manifest Tracking Number

Enter the Manifest Tracking number from Item 4 of the Manifest form to which this continuation sheet is attached.

Item 24. Generator's Name—

Enter the generator's name as it appears in Item 5 on the first page of the Manifest.

Item 25. Transporter—Company Name

If additional transporters are used to transport the waste described on this Manifest, enter the company name of each additional transporter in the order in which they will transport the waste. Enter after the word "Transporter" the order of the transporter. For example, Transporter 3 Company Name. Also enter the U.S. EPA twelve digit identification number of the transporter described in Item 25.

Item 26. Transporter—Company Name

If additional transporters are used to transport the waste described on this Manifest, enter the company name of each additional transporter in the order in which they will transport the waste. Enter after the word "Transporter" the order of the transporter. For example, Transporter 4 Company Name. Each Continuation Sheet can record the names of two additional transporters. Also enter the U.S. EPA twelve digit identification number of the transporter named in Item 26.

Item 27. U.S. D.O.T. Description Including Proper Shipping Name, Hazardous Class, and ID Number (UN/NA)

For each row enter a sequential number under Item 27b that corresponds to the order of waste codes from one continuation sheet to the next, to reflect the total number of wastes being shipped. Refer to instructions for Item 9 of the manifest for the information to be entered.

Item 28. Containers (No. And Type)

Refer to the instructions for Item 10 of the manifest for information to be entered.

Item 29. Total Quantity

Refer to the instructions for Item 11 of the manifest form.

Item 30. Units of Measure (Weight/Volume)

Refer to the instructions for Item 12 of the manifest form.

Item 31. Waste Codes

Refer to the instructions for Item 13 of the manifest form.

Item 32. Special Handling Instructions and Additional Information

Refer to the instructions for Item 14 of the manifest form.

GENERATOR'S INITIAL COPY

Instructions—Continuation Sheet
U.S. EPA Form 8700-22A

Read all instructions before completing this form. This form has been designed for use on a 12-pitch (elite) typewriter; a firm point pen may also be used—press down hard.

This form must be used as a continuation sheet to U.S. EPA Form 8700-22 if:

- More than two transporters are to be used to transport the waste; or
- More space is required for the U.S. DOT descriptions and related information in Item 9 of U.S. EPA Form 8700-22.

Federal regulations require generators and transporters of hazardous waste and owners or operators of hazardous waste treatment, storage, or disposal facilities to use the uniform hazardous waste manifest (EPA Form 8700-22) and, if necessary, this continuation sheet (EPA Form 8700-22A) for both interstate and intrastate transportation.

I. Instructions for Generators

Item 21. Generator's ID Number

Enter the generator's U.S. EPA twelve digit identification number or, the State generator identification number if the generator site does not have an EPA identification number.

Item 22. Page ____

Enter the page number of this Continuation Sheet.

Item 23. Manifest Tracking Number

Enter the Manifest Tracking number from Item 4 of the Manifest form to which this continuation sheet is attached.

Item 24. Generator's Name—

Enter the generator's name as it appears in Item 5 on the first page of the Manifest.

Item 25. Transporter—Company Name

If additional transporters are used to transport the waste described on this Manifest, enter the company name of each additional transporter in the order in which they will transport the waste. Enter after the word "Transporter" the order of the transporter. For example, Transporter 3 Company Name. Also enter the U.S. EPA twelve digit identification number of the transporter described in Item 25.

Item 26. Transporter—Company Name

If additional transporters are used to transport the waste described on this Manifest, enter the company name of each additional transporter in the order in which they will transport the waste. Enter after the word "Transporter" the order of the transporter. For example, Transporter 4 Company Name. Each Continuation Sheet can record the names of two additional transporters. Also enter the U.S. EPA twelve digit identification number of the transporter named in Item 26.

Item 27. U.S. D.O.T. Description Including Proper Shipping Name, Hazardous Class, and ID Number (UN/NA)

For each row enter a sequential number under Item 27b that corresponds to the order of waste codes from one continuation sheet to the next, to reflect the total number of wastes being shipped. Refer to instructions for Item 9 of the manifest for the information to be entered.

Item 28. Containers (No. And Type)

Refer to the instructions for Item 10 of the manifest for information to be entered.

Item 29. Total Quantity

Refer to the instructions for Item 11 of the manifest form.

Item 30. Units of Measure (Weight/Volume)

Refer to the instructions for Item 12 of the manifest form.

Item 31. Waste Codes

Refer to the instructions for Item 13 of the manifest form.

Item 32. Special Handling Instructions and Additional Information

Refer to the instructions for Item 14 of the manifest form.

Cycle Chem, Inc

550 Industrial Drive Lewisberry PA 17339 PHONE: 717-938-4700, FAX:
717-938-3301

Land Disposal Restriction Notification and Certification Form

Generator: US EPA REGION II - SUPERIOR BARREL Manifest Tracking Number: 98727
AND DRUM SITE

EPAID: NJD986630705

Manifest Document Number: 012500266JJK

The EPA hazardous wastes identified below must be treated to the applicable treatment standards set forth in 40 CFR 268.40.

EPA Waste Code Information

Manifest Line	Waste-water?	EPACodes
Page 1 Line 1	No	D001 (Ignitable characteristic wastes subcategory, other than high TOC ignitable liquids)
Page 1 Line 2	No	D001 (Ignitable characteristic wastes subcategory, other than high TOC ignitable liquids)
Page 1 Line 3	No	D001 (Ignitable characteristic wastes subcategory, other than high TOC ignitable liquids), D009 (Low mercury [<260 PPM total mercury] subcategory)
Page 1 Line 4	No	D002
Page 2 Line 1	No	D002
Page 2 Line 2	No	D002
Page 2 Line 3	No	D007, D008 (Lead non-battery subcategory)
Page 2 Line 4	No	D007, D008 (Lead non-battery subcategory)
Page 2 Line 5	No	D002, D009 (Low mercury [<260 PPM total mercury] subcategory)
Page 2 Line 6	No	D002
Page 2 Line 7	No	D002
Page 2 Line 8	No	D002
Page 2 Line 9	No	D001 (High TOC ignitable liquids subcategory), D035
Page 2 Line 10	No	D001 (High TOC ignitable liquids subcategory), D035
Page 3 Line 1	No	D001 (High TOC ignitable liquids subcategory), D008 (Lead non-battery subcategory), D035, D039
Page 3 Line 2	No	D001 (High TOC ignitable liquids subcategory), D008 (Lead non-battery subcategory), D035, D039

Underlying Hazardous Constituents

(None present unless identified below.)

Manifest Line	Constituents
---------------	--------------

I certify that all information submitted On this Land Disposal Restriction and Certification Form is accurate and complete, to the best of my knowledge and information.

Signature: Margaret Gregor

Name: Margaret Gregor

Title: On-Scene Coordinator

Date: 02/06/2014

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator ID Number	2. Page 1 of	3. Emergency Response Phone	4. Manifest Tracking Number			
		NJD986630708	1	800-424-8602 +410-368-5170	012500207 JJK			
5. Generator's Name and Mailing Address US EPA REGION II - SUPERIOR 2890 WOODBRIDGE AVENUE EDISON, NJ 07026								
Generator's Site Address (if different than mailing address) 798 JACOB HARRIS LANE ELK TOWNSHIP NJ 08028								
6. Transporter 1 Company Name CLEAN VENTURE INC.								
U.S. EPA ID Number NJ0000027193								
7. Transporter 2 Company Name								
U.S. EPA ID Number								
8. Designated Facility Name and Site Address CYCLE CHEM, INC. 350 INDUSTRIAL DRIVE LEWISBERRY, PA 17339								
Facility's Phone: (717) 938-4700								
U.S. EPA ID Number PA0067098822								
GENERATOR	9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	10. Containers		11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes	
			No.	Type				
		1. NON DOT / NON RCRA REGULATED MATERIAL	XX13	TP	3,360 G		NONE	
		2. NON DOT / NON RCRA REGULATED MATERIAL	XX14	DM	1,445 G		NONE	
		3. NON DOT / NON RCRA REGULATED MATERIAL	XX6	DF	570 G		NONE	
	4. NON DOT / NON RCRA REGULATED MATERIAL	XX1	DF	15 G		NONE		
14. Special Handling Instructions and Additional Information JOBG/JOB/562650/98511 (1)LS-C ITEM C - WASTE INORGANIC LIQUID (2)LS-C ITEM C - WASTE INORGANIC LIQUID (3)LS-C ITEM C - WASTE INORGANIC LIQUID (4)LS-C ITEM C - WASTE INORGANIC LIQUID								
15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.								
Generator's/Offor's Printed/Typed Name Margaret Grish, On-Site Coordinator								
Signature Margaret Grish								
Month Day Year 01 30 2004								
INTL	16. International Shipments <input type="checkbox"/> Import to U.S. <input type="checkbox"/> Export from U.S. Port of entry/exit: Date leaving U.S.:							
	Transporter signature (for exports only):							
TRANSPORTER	17. Transporter Acknowledgment of Receipt of Materials							
	Transporter 1 Printed/Typed Name BROCK A SHERIFF							
Signature Brock A Sheriff								
Month Day Year 01 30 14								
DESIGNATED FACILITY	18. Discrepancy							
	18a. Discrepancy Indication Space <input type="checkbox"/> Quantity <input type="checkbox"/> Type <input type="checkbox"/> Residue <input type="checkbox"/> Partial Rejection <input type="checkbox"/> Full Rejection							
	Manifest Reference Number:							
	18b. Alternate Facility (or Generator) U.S. EPA ID Number							
	Facility's Phone:							
18c. Signature of Alternate Facility (or Generator)								
Month Day Year								
19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)								
1. 2. 3. 4.								
20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a								
Printed/Typed Name								
Signature								
Month Day Year								

U.S. EPA Form 8700-22

Read all instructions before completing this form.

1. This form has been designed for use on a 12-pitch (elite) typewriter which is also compatible with standard computer printers; a firm point pen may also be used—press down hard.
2. Federal regulations require generators and transporters of hazardous waste and owners or operators of hazardous waste treatment, storage, and disposal facilities to complete this form (EPA Form 8700-22) and, if necessary, the continuation sheet (EPA Form 8700-22A) for both inter- and intrastate transportation of hazardous waste.

Public reporting burden for this collection of information is estimated to average: 30 minutes for generators, 10 minutes for transporters, and 25 minutes for owners or operators of treatment, storage, and disposal facilities. This includes time for reviewing instructions, gathering data, completing, reviewing and transmitting the form. Any correspondence regarding the PRA burden statement for the manifest must be sent to the Director of the Collection Strategies Division in EPA's Office of Information Collection at the following address: U.S. Environmental Protection Agency (2822T), 1200 Pennsylvania Ave., NW., Washington, DC 20460. Do not send the completed form to this address.

I. Instructions for Generators

Item 1. Generator's U.S. EPA Identification Number

Enter the generator's U.S. EPA twelve digit identification number, or the State generator identification number if the generator site does not have an EPA identification number.

Item 2. Page 1 of ____

Enter the total number of pages used to complete this Manifest (i.e., the first page (EPA Form 8700-22) plus the number of Continuation Sheets (EPA Form 8700-22A), if any).

Item 3. Emergency Response Phone Number

Enter a phone number for which emergency response information can be obtained in the event of an incident during transportation. The emergency response phone number must:

1. Be the number of the generator or the number of an agency or organization who is capable of and accepts responsibility for providing detailed information about the shipment;
2. Reach a phone that is monitored 24 hours a day at all times the waste is in transportation (including transportation related storage); and
3. Reach someone who is either knowledgeable of the hazardous waste being shipped and has comprehensive emergency response and spill cleanup/incident mitigation information for the material being shipped or has immediate access to a person who has that knowledge and information about the shipment.

Note: Emergency Response phone number information should only be entered in Item 3 when there is one phone number that applies to all the waste materials described in Item 9b. If a situation (e.g., consolidated shipments) arises where more than one Emergency Response phone number applies to the various wastes listed on the manifest, the phone numbers associated with each specific material should be entered after its description in Item 9b.

Item 4. Manifest Tracking Number

This unique tracking number must be pre-printed on the manifest by the forms printer.

Item 5. Generator's Mailing Address, Phone Number and Site Address

Enter the name of the generator, the mailing address to which the completed manifest signed by the designated facility should be mailed, and the generator's telephone number. Note, the telephone number (including area code) should be the normal business number for the generator, or the number where the generator or his authorized agent may be reached to provide instructions in the event the designated and/or alternate (if any) facility rejects some or all of the shipment. Also enter the physical site address from which the shipment originates only if this address is different than the mailing address.

Item 6. Transporter 1 Company Name, and U.S. EPA ID Number

Enter the company name and U.S. EPA ID number of the first transporter who will transport the waste. Vehicle or driver information may not be entered here.

Item 7. Transporter 2 Company Name and U.S. EPA ID Number

If applicable, enter the company name and U.S. EPA ID number of the second transporter who will transport the waste. Vehicle or driver information may not be entered here.

If more than two transporters are needed, use a Continuation Sheet(s) (EPA Form 8700-22A).

Item 8. Designated Facility Name, Site Address, and U.S. EPA ID Number

Enter the company name and site address of the facility designated to receive the waste listed on this manifest. Also enter the facility's phone number and the U.S. EPA twelve digit identification number of the facility.

Item 9. U.S. DOT Description (Including Proper Shipping Name, Hazard Class or Division, Identification Number, and Packing Group)

Item 9a. If the wastes identified in Item 9b consist of both hazardous and nonhazardous materials, then identify the hazardous materials by entering an "X" in this Item next to the corresponding hazardous material identified in Item 9b.

Item 9b. Enter the U.S. DOT Proper Shipping Name, Hazard Class or Division, Identification Number (UN/NA) and Packing Group for each waste as identified in 49 CFR 172. Include technical name(s) and reportable quantity references, if applicable.

Note: If additional space is needed for waste descriptions, enter these additional descriptions in Item 27 on the Continuation Sheet (EPA Form 8700-22A). Also, if more than one Emergency Response phone number applies to the various wastes described in either Item 9b or Item 27, enter applicable Emergency Response phone numbers immediately following the shipping descriptions for those items.

Item 10. Containers (Number and Type)

Enter the number of containers for each waste and the appropriate abbreviation from Table I (below) for the type of container.

TABLE I.—TYPES OF CONTAINERS

BA = Burlap, cloth, paper, or plastic bags.	DT = Dump truck.
CF = Fiber or plastic boxes, cartons, cases.	DW = Wooden drums, barrels, kegs.
CM = Metal boxes, cartons, cases (including roll-offs).	HG = Hopper or gondola cars.
CW = Wooden boxes, cartons, cases.	TC = Tank cars.
CY = Cylinders.	TP = Portable tanks.
DF = Fiberboard or plastic drums, barrels, kegs.	TT = Cargo tanks (tank trucks).
DM = Metal drums, barrels, kegs.	

Item 11. Total Quantity

Enter, in designated boxes, the total quantity of waste. Round partial units to the nearest whole unit, and do not enter decimals or fractions. To the extent practical, report quantities using appropriate units of measure that will allow you to report quantities with precision. Waste quantities entered should be based on actual measurements or reasonably accurate estimates of actual quantities shipped. Container capacities are not acceptable as estimates.

Item 12. Units of Measure (Weight/Volume)

Enter, in designated boxes, the appropriate abbreviation from Table II (below) for the unit of measure.

TABLE II.—UNITS OF MEASURE

G = Gallons (liquids only).	N = Cubic Meters.
K = Kilograms.	P = Pounds.
L = Liters (liquids only).	T = Tons (2000 Pounds).
M = Metric Tons (1000 kilograms).	Y = Cubic Yards.

Note: Tons, Metric Tons, Cubic Meters, and Cubic Yards should only be reported in connection with very large bulk shipments, such as rail cars, tank trucks, or barges.

Item 13. Waste Codes

Enter up to six federal and state waste codes to describe each waste stream identified in Item 9b. State waste codes that are not redundant with federal codes must be entered here, in addition to the federal waste codes which are most representative of the properties of the waste.

Item 14. Special Handling Instructions and Additional Information

1. Generators may enter any special handling or shipment-specific information necessary for the proper management or tracking of the materials under the generator's or other handler's business processes, such as waste profile numbers, container codes, bar codes, or response guide numbers. Generators also may use this space to enter additional descriptive information about their shipped materials, such as chemical names, constituent percentages, physical state, or specific gravity of wastes identified with volume units in Item 12.
2. This space may be used to record limited types of federally required information for which there is no specific space provided on the manifest, including any alternate facility designations; the manifest tracking number of the original manifest for rejected wastes and residues that are re-shipped under a second manifest; and the specification of PCB waste descriptions and PCB out-of-service dates required under 40 CFR 761.207. Generators, however, cannot be required to enter information in this space to meet state regulatory requirements.

Item 15. Generator's/Officer's Certifications

1. The generator must read, sign, and date the waste minimization certification statement. In signing the waste minimization certification statement, those generators who have not been exempted by statute or regulation from the duty to make a waste minimization certification under section 3002(b) of RCRA are also certifying that they have complied with the waste minimization requirements. The Generator's Certification also contains the required attestation that the shipment has been properly prepared and is in proper condition for transportation (the shipper's certification). The content of the shipper's certification statement is as follows: "I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent." When a party other than the generator prepares the shipment for transportation, this party may also sign the shipper's certification statement as the offeror of the shipment.
2. Generator or Offeror personnel may preprint the words, "On behalf of" in the signature block or may hand write this statement in the signature block prior to signing the generator/offeror certification, to indicate that the individual signs as the employee or agent of the named principal.

Note: All of the above information except the handwritten signature required in Item 15 may be pre-printed.



Estimated Cost For Waste Disposal

Date Printed: 1/22/14 **Estimate Number:** 5118-1 **GLASSBORO, NJ BID** **Sales Code:** JOB

Contact: Raymond Veronneau **Phone:** (203) 393-0035 **Fax:** (203) 393-0053

Customer: JOB-American Waste Management Services, Inc. **Email:** rveronneau@awmsi.com

Product Code	Description
WR3	ITEM A
	Final Treatment via Incineration at Ross Incineration Services, Inc. or other Cyclechem approved facility.
WDV	ITEM B
	Final Treatment via Deepwell Injection at Vickery Environmental or other Cyclechem approved facility.
WDV	ITEM B
	Final Treatment via Deepwell Injection at Vickery Environmental or other Cyclechem approved facility.
WDV	ITEM B
	Final Treatment via Deepwell Injection at Vickery Environmental or other Cyclechem approved facility.
WDV	ITEM B
	Final Treatment via Deepwell Injection at Vickery Environmental or other Cyclechem approved facility.
LS	ITEM C
	Final Treatment via Solidify/Landfill at Cumberland County Landfill (IWS) or other Cyclechem approved facility.
LS	ITEM C
	Final Treatment via Solidify/Landfill at Cumberland County Landfill (IWS) or other Cyclechem approved facility.
LS	ITEM C
	Final Treatment via Solidify/Landfill at Cumberland County Landfill (IWS) or other Cyclechem approved facility.
LS	ITEM C
	Final Treatment via Solidify/Landfill at Cumberland County Landfill (IWS) or other Cyclechem approved facility.
WR3	ITEM D
	Final Treatment via Incineration at Ross Incineration Services, Inc. or other Cyclechem approved facility.
WR3	ITEM D
	Final Treatment via Incineration at Ross Incineration Services, Inc. or other Cyclechem approved facility.
WDV	ITEM E
	Final Treatment via Deepwell Injection at Vickery Environmental or other Cyclechem approved facility.
WDV	ITEM E
	Final Treatment via Deepwell Injection at Vickery Environmental or other Cyclechem approved facility.

New Jersey TSDF
 217 South First Street
 Elizabeth, NJ 07208
 908-355-5800
 FAX: 908-355-0562

Corporate Office
 201 South First Street
 Elizabeth, NJ 07208
 908-355-5800
 FAX: 908-355-3495
www.cyclechem.com

Pennsylvania TSDF
 550 Industrial Drive
 Lewisberry, PA 17339
 717-938-4700
 FAX: 717-938-3301



WDV	ITEM F	
Final Treatment via Deepwell Injection at Vickery Environmental or other Cyclechem approved facility.		
WDV	ITEM F	
Final Treatment via Deepwell Injection at Vickery Environmental or other Cyclechem approved facility.		
WDV	ITEM G	
Final Treatment via Deepwell Injection at Vickery Environmental or other Cyclechem approved facility.		
WDV	ITEM G	
Final Treatment via Deepwell Injection at Vickery Environmental or other Cyclechem approved facility.		
WDV	ITEM H	
Final Treatment via Deepwell Injection at Vickery Environmental or other Cyclechem approved facility.		
WDV	ITEM H	
Final Treatment via Deepwell Injection at Vickery Environmental or other Cyclechem approved facility.		
WDV	ITEM H	
Final Treatment via Deepwell Injection at Vickery Environmental or other Cyclechem approved facility.		
WDV	ITEM I	
Final Treatment via Deepwell Injection at Vickery Environmental or other Cyclechem approved facility.		
WDV	ITEM I	
Final Treatment via Deepwell Injection at Vickery Environmental or other Cyclechem approved facility.		
WR3	ITEM J	
Final Treatment via Incineration at Ross Incineration Services, Inc. or other Cyclechem approved facility.		
WR3	ITEM J	
Final Treatment via Incineration at Ross Incineration Services, Inc. or other Cyclechem approved facility.		
WDV	ITEM K	
Final Treatment via Deepwell Injection at Vickery Environmental or other Cyclechem approved facility.		
WDV	ITEM K	
Final Treatment via Deepwell Injection at Vickery Environmental or other Cyclechem approved facility.		
SSM	ITEM L	
Final Treatment via Incineration at Ross Incineration Services, Inc. or other Cyclechem approved facility.		
SSM	ITEM L	
Final Treatment via Incineration at Ross Incineration Services, Inc. or other Cyclechem approved facility.		
SSM	ITEM L	
Final Treatment via Incineration at Ross Incineration Services, Inc. or other Cyclechem approved facility.		
WDV	ITEM M	
Final Treatment via Deepwell Injection at Vickery Environmental or other Cyclechem approved facility.		
SSM	ITEM N	
Final Treatment via Incineration at Ross Incineration Services, Inc. or other Cyclechem approved facility.		
SSM	ITEM O	
Final Treatment via Incineration at Ross Incineration Services, Inc. or other Cyclechem approved facility.		
CIB	ITEM P	
Final Treatment via Aqueous Treatment at EQ of Detroit, Inc. or other Cyclechem approved facility.		

New Jersey TSDF
217 South First Street
Elizabeth, NJ 07206
908-355-5800
FAX: 908-355-0562

Corporate Office
201 South First Street
Elizabeth, NJ 07206
908-355-5800
FAX: 908-355-3495
www.cyclechem.com

Pennsylvania TSDF
550 Industrial Drive
Lewisberry, PA 17339
717-938-4700
FAX: 717-938-3301



CIB	ITEM P	
Final Treatment via Aqueous Treatment at EQ of Detroit, Inc. or other Cyclechem approved facility.		
LJES	ITEM Q	
Final Treatment via Stabilization/Landfill at ENVIROSAFE SERVICES OF OHIO, INC or other Cyclechem approved facility.		
CIB	ITEM R	
Final Treatment via Aqueous Treatment at EQ of Detroit, Inc. or other Cyclechem approved facility.		
CIA	ITEM S	
Final Treatment via Aqueous Treatment at EQ of Detroit, Inc. or other Cyclechem approved facility.		
CIA	ITEM S	
Final Treatment via Aqueous Treatment at EQ of Detroit, Inc. or other Cyclechem approved facility.		
COA	ITEM T	
Final Treatment via Aqueous Treatment at EQ of Detroit, Inc. or other Cyclechem approved facility.		
WDV	ITEM U	
Final Treatment via Deepwell Injection at Vickery Environmental or other Cyclechem approved facility.		
SSM	ITEM V	
Final Treatment via Incineration at Ross Incineration Services, Inc. or other Cyclechem approved facility.		
SSM	ITEM W	
Final Treatment via Incineration at Ross Incineration Services, Inc. or other Cyclechem approved facility.		
SSM	ITEM W	
Final Treatment via Incineration at Ross Incineration Services, Inc. or other Cyclechem approved facility.		

Could also go to:

Max Environmental Technologies, Inc.

Modern Landfill and Recycling

New Jersey TSDf
217 South First Street
Elizabeth, NJ 07208
908-355-5800
FAX: 908-355-0562

Corporate Office
201 South First Street
Elizabeth, NJ 07208
908-355-5800
FAX: 808-355-3485
www.cyclechem.com

Pennsylvania TSDf
550 Industrial Drive
Lewisberry, PA 17339
717-938-4700
FAX: 717-938-3301